



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMH 6379Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT LH DOOR	DENTED/WARPED	\$2,573.90	\$2,573.90
1	SET FRONT LH DOOR FRAME STICKER	NECESSARY	\$280.40	\$280.40
1	LH SLIDING DOOR	BENT	\$2,791.60	\$2,791.60
1	SET LH SLIDING DOOR FRAME STICKER	NECESSARY	\$148.70	\$148.70
1	LH SLIDING DOOR RUBBER	SERVICEABLE	\$1,785.70	\$0.00
1	LH SIDE SKIRT	DENTED/CUT	\$1,168.90	\$1,168.90
1	REAR BUMPER	CRACKED	\$836.70	\$836.70
1	REAR BUMPER LH RETAINER	SERVICEABLE	\$121.30	\$0.00
6	REAR BUMPER CLIPS @\$3.50	NECESSARY	\$21.00	\$21.00
	<b>LESS 25.00% DISCOUNT</b>		(\$2,432.05)	(\$1,955.30)
			<b>\$7,296.15</b>	<b>\$5,865.90</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR LH SPORT RIM (LOCAL REPAIR) (SN)	DENTED	\$1,889.55	\$150.00
			<b>\$1,889.55</b>	<b>\$150.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE AND REFIT FT LH DOOR GLASS		\$60.00	\$60.00
	REMOVE AND REFIT LH SLIDING DOOR GLASS		\$60.00	\$60.00
	REMOVE AND REFIT FRT LH DOOR, SLIDING DOOR AND TRANSFER ATTACHMENTS, LH SIDE SKIR, REAR BUMPER. TO KNOCK AND REPAIR REAR LH FENDER AND REALIGN THE SAME		\$800.00	\$600.00
	PUTTY AND RESPRAY ON FRT LH DOOR, SLIDING DOOR, REAR LH FENDER, LH SIDE SKIRT, ROCKER AND REAR BUMPER		\$1,200.00	\$1,000.00
	RUSTPROOFING		\$60.00	\$60.00
			<b>\$2,180.00</b>	<b>\$1,780.00</b>

<b>GRAND TOTAL</b>			<b>\$11,365.70</b>	<b>\$7,795.90</b>
--------------------	--	--	--------------------	-------------------

	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>\$6,200.00</b>
--	---	--	--	-------------------

Report Ref No: CS/FCI24090371/Kvp3m4



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## **KSC**

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.