



發 福 摩 哆 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO. 375654/000

Not Affected
near
23/9/24
2/585300/
5-dys
whgpt. Hocky..

Carplate: GBG8521A
Chassis No: KDH2010232194
Accident Date: 19/09/2024
Make & Model: Toyota HiAce

No.	Item	Nett Price	✓/✗	Remarks
1	Rear Tailgate	\$ 2,162.70		Bodywork ✓
2	Rear Tailgate Lock Assembly	\$ 509.40	40% SD	20/5m ✓
3	Rear Tailgate Weatherstrip	\$ 399.35		7m/10m ✓
4	Rear Tailgate Logo "  "	\$ 76.30		new ✓
5	Rear Tailgate Trim Board	\$ 490.10		11 X
6	Rear End Panel (inner)	\$ 451.90		Bodywork ✓
7	Rear End Panel (outer)	\$ 545.10		Bodywork ✓
8	Rear End Panel Top Garnish	\$ 292.10		NTX
9	Rear Bumper	\$ 547.20		Dis ✓
10	Rear Bumper Side Retainer RH	\$ 120.60		11 X
11	Rear Taillamp Corner Panel RH	\$ 150.40		RX
12	Taillamp RH	\$ 338.90		2R ✓
13	Rear Bumper Side Retainer LH	\$ 120.60		2R ✓
14	Rear Taillamp Corner Panel LH	\$ 150.40		RX
15	Taillamp LH	\$ 338.90		2R ✓
16	Rear Floor Panel	\$ 1,766.20		RX
17	Rear Windscreen Moulding	\$ 121.60		NSX
18	Rear Tailgate Center Garnish (Chrome)	\$ 312.80		11 X
19	Rear Carplate Lamp LH	\$ 38.60		11 X
20	Rear Carplate Lamp RH	\$ 38.60		11 X
21	Rear Tailgate Wooden Board	\$ 435.10		11 X
22	Exhaust Pipe and Box	\$ 1,680.20		11 X
23	Rear Step-up Panel	\$ 319.60		Bar ✓
24				
25				
26				
27				
28				
29				
30				
31				
32				
33				
34				
35				
36				
37				

	Special Nett Items	Price	✓/✗	Remarks
1	Rear Bumper Clips (1 Set)	\$ 40.00		net 30 s/n
2	Rear Tailgate Wooden Board Clips (1 Set)	\$ 40.00		11 X
3	Rear Reverse Sensor (1 Set)	\$ 280.00		no. 1 factor 200 s/n
4	End Panel Sealant	\$ 100.00		net 40 s/n
5	Tailgate Sticker "70km/hr"	\$ 20.00		net 10 s/n
6	Tailgate Customisable Sticker (Company Logo English)	\$ 280.00	}	380 s/n
7	Tailgate Customisable Sticker (Company Logo Chinese)	\$ 280.00		
8	Tailgate Customisable Sticker (Company Logo Bread)	\$ 380.00		
9	Tailgate Customisable Sticker (Company Logo 1989)	\$ 180.00		
10	Rear Floor Panel Aluminium Board	\$ 1,580.00		11 X
11	Rear Number Plate and Casing	\$ 70.00		5 CR 40 s/n
12	Rear Windscreen Sealant	\$ 120.00		net 40 s/n
13	Rear Reverse Camera (1 Set)	\$ 380.00		11 X
14	Tailgate Sticker "HIACE"	\$ 75.00		net 40 s/n
15				
No.	All Necessary Work	Price	✓/✗	Remarks
1	To Carry Out Anti-rust Treatment	\$ 120.00		50
2	Remove and Refit All Trims, Upholders, Garnish and All Necessary to Facilitate Repair Works	\$ 320.00		11 X
3	Transfer of Tailgate Mechanism	\$ 120.00		50
4	Remove and Install New Reverse Sensor	\$ 150.00		30
5	Remove and Transfer of Tailgate Windscreen	\$ 180.00		100
6	To Apply All Necessary Stickers	\$ 250.00		11 X
7	Labour to remove and replace damaged parts (Including refitting and repositioning of replaced parts)	\$ 1,250.00		800
8	Spray painting materials and respray of all affected and replaced parts necessary for paintwork	\$ 1,100.00		600
	Estimated No. of days for repairs and respray of all necessary	8 Days		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-5 709.05
52
4281.79
780
1630
6691.79
211
530.0