

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/C7124090372/unh3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GAG 8521Aat Workshop m/s Huot mode

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$ 40k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No**CA / REV / REP. / 24 HRS** 3 300CDate: _____ Person Contacted: LTA 67078

Vehicle: IN / OUT

Veh No: GAG 8521A Yr Regn: 22/11/17Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**Truck / Trailer or CA7Make: Toyota Hiace DX-3.0 2982Colour: white A/C: **Insured / Std / NI / NA**Sp. Reading: 215279 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: KDM 2010 232194Gen. Cond: **Good / Fair / Poor / Burnt**Steering: **Inorder / Jammed / Leaked / Burnt** orBrake: **Inorder / Jammed / Leaked / Burnt** orModi: **Nil / S/Rim / STD A/Rim** orTyre Size: **F:** 195-275**R:** _____**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /****TOYO / YOKO** or AS 115Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 19/09/24 D.O.I. 23/09/24

Survey held at _____

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** orRearThe **U/C / Chassis frame / Body Structure** affected due to collision.Date / Time Action / Instruction 1/10/24 1/5 @ 5300 inbnd David 26-09-24 pass out.

(Red. \$ 16273.31, 75%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$) S + RS, SI

Transportation:

☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$) _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	300C
Vehicle Details	
Vehicle No.:	GBG8521A
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Sep 2024
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 3.0 AUTO
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	1KD2746761
Chassis No.:	KDH2010232194
Maximum Power Output:	-
Open Market Value:	\$31,992.00
Original Registration Date:	22 Nov 2017
First Registration Date:	22 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$1,600.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Nov 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$22,377.00
COE Rebate Amount:	\$7,078.00
Total Rebate Amount:	\$7,078.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 23 Sep 2024

OK



PREMIUM AD

Toyota Hiace 3.0M
DX

\$46,300
Instl. \$1,240
/mth

\$14,380 /yr
Diesel

13-Dec-2017
(3yrs 2mths COE left)

N.Air 2,982 cc 3 Owners



Well kept. Selling cheap.

Think One Automobile & Trading|Posted 19-Sep-2024

☐ Compare



PREMIUM AD

Toyota Hiace 3.0M
DX

\$35,800
Instl. \$1,162
/mth

\$13,540 /yr
Diesel

17-May-2017
(2yrs 7mths COE left)

N.Air 2,982 cc 1 Owner



Well maintained vehicle. 1 owner only. High loan applicable & trade in acceptable.

Contact our sales team now!

Think One Automobile & Trading|Posted 18-Sep-2024

☐ Compare



★ StarAd View All

Mazda 3 1.5A Deluxe Sunroof.

Highest Specifications Mazda 3 Equipped. Direct Owner

[CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES]



PRIME MOTOR
& LEASING

With over 200 units of vehicles to choose from,
ranging from all European to Japanese Makes.



HIN LUNG AUTO PTE LTD

One Stop Car Hub

Finance, Insurance, Workshop New and Us



PREMIUM AD

Toyota Hiace 3.0M
DX

\$38,988
Instl. \$1,159
/mth

\$13,680 /yr
Diesel

31-Jul-2017
(2yrs 10mths COE left)

N.Air 2,982 cc 3 Owners



High specs unit! Comes with LED headlights and rear aircon! Tip-top condition, powerful engine, smooth gears! Bonus new paintwork freshly done, plywood+box up with carpet, all wear and tear replaced! \$168 Lifetime Servicing + 2 Years Unlimited Mileage Warranty! 100% loan no problem! We offer highest trade in for your current vehicle! Call to secure this masterpiece now before it's gone!

ABS Bus Pte Ltd|Posted 17-Sep-2024

☐ Compare



PREMIUM AD

Toyota Hiace 3.0M
DX

\$42,500
Instl. \$1,138
/mth

\$13,350 /yr
Diesel

30-Nov-2017
(3yrs 2mths COE left)

N.Air 2,982 cc 1 Owner



Well maintained vehicle. 1 owner only. High loan applicable & trade in acceptable.

Contact our sales team now.

Think One Automobile & Trading|Posted 17-Sep-2024

☐ Compare

Compare



發 福 摩 哆 車 房
HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO. 375654/000

Not pulled
near
23/9/24
2/585300/
5 days
whgpt. Mhany.

Carplate: GBG8521A
Chassis No: KDH2010232194
Accident Date: 19/09/2024
Make & Model: Toyota HiAce

No.	Item	Nett Price	✓/✗	Remarks
1	Rear Tailgate	\$ 2,162.70		Body 300 ✓
2	Rear Tailgate Lock Assembly	\$ 509.40	408.50	20/50 ✓
3	Rear Tailgate Weatherstrip	\$ 399.35		7w/1011 ✓
4	Rear Tailgate Logo " Toyota "	\$ 76.30		new ✓
5	Rear Tailgate Trim Board	\$ 490.10		11 X
6	Rear End Panel (inner)	\$ 451.90		Body 100 ✓
7	Rear End Panel (outer)	\$ 545.10		Body 100 ✓
8	Rear End Panel Top Garnish	\$ 292.10		N7X
9	Rear Bumper	\$ 547.20		Dis ✓
10	Rear Bumper Side Retainer RH	\$ 120.60		11 X
11	Rear Taillamp Corner Panel RH	\$ 150.40		RX
12	Taillamp RH	\$ 338.90		2R ✓
13	Rear Bumper Side Retainer LH	\$ 120.60		2R ✓
14	Rear Taillamp Corner Panel LH	\$ 150.40		RX
15	Taillamp LH	\$ 338.90		2R ✓
16	Rear Floor Panel	\$ 1,766.20		RX
17	Rear Windscreen Moulding	\$ 121.60		N5X
18	Rear Tailgate Center Garnish (Chrome)	\$ 312.80		11 X
19	Rear Carplate Lamp LH	\$ 38.60		11 X
20	Rear Carplate Lamp RH	\$ 38.60		11 X
21	Rear Tailgate Wooden Board	\$ 435.10		11 X
22	Exhaust Pipe and Box	\$ 1,680.20		11 X
23	Rear Step-up Panel	\$ 319.60		Body ✓
24				
25				
26				
27				
28				
29				
30				
31				
32				
33				
34				
35				
36				
37				

	<u>Special Nett Items</u>	Price	☒ / ☒	Remarks
1	Rear Bumper Clips (1 Set)	\$ 40.00		net 30 s/n
2	Rear Tailgate Wooden Board Clips (1 Set)	\$ 40.00		11 X
3	Rear Reverse Sensor (1 Set)	\$ 280.00		no. 1 factor 200 s/n
4	End Panel Sealant	\$ 100.00		net 40 s/n
5	Tailgate Sticker "70km/hr"	\$ 20.00		net 10 s/n
6	Tailgate Customisable Sticker (Company Logo English)	\$ 280.00	}	
7	Tailgate Customisable Sticker (Company Logo Chinese)	\$ 280.00		380 s/n
8	Tailgate Customisable Sticker (Company Logo Bread)	\$ 380.00		
9	Tailgate Customisable Sticker (Company Logo 1989)	\$ 180.00		
10	Rear Floor Panel Aluminium Board	\$ 1,580.00		11 X
11	Rear Number Plate and Casing	\$ 70.00		SCR 40 s/n
12	Rear Windscreen Sealant	\$ 120.00		net 40 s/n
13	Rear Reverse Camera (1 Set)	\$ 380.00		11 X
14	Tailgate Sticker "HIACE"	\$ 75.00		net 40 s/n
15				
No.	All Necessary Work	Price	☒ / ☒	Remarks
1	To Carry Out Anti-rust Treatment	\$ 120.00		50
2	Remove and Refit All Trims, Upholders, Garnish and All Necessary to Facilitate Repair Works	\$ 320.00		11 X
3	Transfer of Tailgate Mechanism	\$ 120.00		50
4	Remove and Install New Reverse Sensor	\$ 150.00		30
5	Remove and Transfer of Tailgate Windscreen	\$ 180.00		100
6	To Apply All Necessary Stickers	\$ 250.00		11 X
7	Labour to remove and replace damaged parts (Including refitting and repositioning of replaced parts)	\$ 1,250.00		800
8	Spray painting materials and respray of all affected and replaced parts necessary for paintwork	\$ 1,100.00		600
	Estimated No. of days for repairs and respray of all necessary	8 Days		

21573.31

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts, Labour survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-5709.05
 52
 4281.79
 780
 1630
 6691.79
 211
 5300