

ASS. REC. BY:

REF:

CS/11124090374/Knp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLM 28536 Yr Regn: 03, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda HRV c.c. 1496

Colour:

M. Green A/C: Insured / Std / NI / NA

Sp. Reading

83487 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9 mm

R/Bal.

9 mm

L/Bal.

9 mm

L/Bal.

9 mm

D.O.A.

18/9/24

D.O.A.

23/9/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/9 11:20, 8350d Caber (Red. \$10152.32, 74%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

NOT Authorized
 11 Bay @ 350dp
 Resurvey After Paint
 5 days

EM Solution Pte Ltd

160 Sin Ming Drive, (Sin Ming Autocity), #03-18/19, Singapore 575722

H/P: 9004 2254 (Derek Keh) Tel: 6456 0226 Fax: 6458 4500

Email: emaautosolution@singnet.com.sg

Vehicle number: SLM2853G

Vehicle Made & Model: HONDA HRV

Qty	List Items	Amount \$
1	Tailgate <i>1100.70</i>	1,287.10 ✓
1 set	Tailgate glass moulding	121.60 ✓
1	Tailgate outer garnish	391.40 X
1	Tailgate emblem logo	48.80 X
1	Tailgate emblem "HRV"	68.80 ✓
1	Tailgate emblem "i-VTEC"	68.80 ✓
2	Tailgate lamps - L/R @ 410.20	820.40 X
1	Tailgate inner lock <i>131.80</i>	281.30 ✓
1	Tailgate inner trim board	481.60 X
1	Tailgate inner pull pocket	86.90 X
1	Tailgate w/strip <i>168.40</i>	210.20 <i>508.00 84.20</i>
2	Tailgate dampers - L/R @ 186.10	372.20 X
2	Tailgate stoppers @ 12.60	25.20 X
2	Taillamps - L/R @ 488.10	976.20 X
1	Rear bumper	791.60 ✓
2	Rear bumper reflectors - L/R @ 89.90	179.80 X
2	Rear bumper sides - L/R @ 241.20	482.40 X
2	Rear bumper side retainers - L/R @ 48.60	97.20 X
1	Rear end panel <i>517</i>	659.10 ✓
1	Rear end panel garnish <i>160.50</i>	211.60 ✓
1	Rear exhaust silencer	576.50 X
1	Rear exhaust insulator	120.30 X
2	Rear exhaust mountings @ 28.20	56.40 X
1	Rear floor board	370.60 X
1	Rear floor sponge tray	321.60 X
1	Rear floor panel	871.90 X
1	Rear floor panel undercover	286.90 X
2	Rear fender protectors - L/R @ 341.60	683.20 X
1	Rear smart keyless antenna <i>85.20</i>	191.20 ✓
1	Rear smart keyless buzzle	199.60 X
Sub-total		11,340.40
Less 20%		2,268.08
Total List		9,072.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to first approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle number: SLM2853G

Vehicle Made & Model: HONDA HRV

Special Nett Items

1 set Tailgate glass sealant
1 set Tailgate outer garnish clip
1 set Rear bumper clip
1 set Rear no. plate
1 Rear reverse camera
1 set Rear reverse sensor - 4 Pcs

<i>nn</i>	80.00	<i>405A</i>
<i>nn</i>	80.00	<i>X</i>
<i>nn</i>	50.00	<i>✓</i>
<i>nn</i>	60.00	<i>X</i>
<i>nn</i>	450.00	<i>X</i>
<i>Del/Short</i>	480.00	<i>✓ 2005W</i>
Total Special Nett	1,200.00	

Labour charges

To check rear electrical wiring
To remove, refix tailgate glass
Transfer & reinstall tailgate components to new tailgate
To remove, refix rear interior trims to assist repair
To remove, refix rear reverse sensor / camera
To remove, refix rear exhaust
To respray undercoating
To respray painting and etc
Panel beating, cut, weld remove & replacing above parts

	50.00	<i>201</i>
	180.00	<i>1201</i>
	150.00	<i>601</i>
	120.00	<i>601</i>
	80.00	<i>601</i>
<i>nn</i>	80.00	<i>X</i>
	120.00	<i>601</i>
	1,200.00	<i>6001</i>
	1,400.00	<i>6001</i>
Total Labour	3,380.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 13,652.32