

Not Authorized
 11 May 8350dp
 Resurvey After Paint
 5 days

EM Solution Pte Ltd

160 Sin Ming Drive, (Sin Ming Autocity), #03-18/19, Singapore 575722

H/P: 9004 2254 (Derek Keh) Tel: 6456 0226 Fax: 6458 4500

Email: emautosolution@singnet.com.sg

Vehicle number: SLM2853G

Vehicle Made & Model: HONDA HRV

Qty	List Items
1	Tailgate <i>1100.70</i>
1 set	Tailgate glass moulding
1	Tailgate outer garnish
1	Tailgate emblem logo
1	Tailgate emblem "HRV"
1	Tailgate emblem "i-VTEC"
2	Tailgate lamps - L/R @ 410.20
1	Tailgate inner lock <i>131.80</i>
1	Tailgate inner trim board
1	Tailgate inner pull pocket
1	Tailgate w/strip <i>168.40</i>
2	Tailgate dampers - L/R @ 186.10
2	Tailgate stoppers @ 12.60
2	Taillamps - L/R @ 488.10
1	Rear bumper
2	Rear bumper reflectors - L/R @ 89.90
2	Rear bumper sides - L/R @ 241.20
2	Rear bumper side retainers - L/R @ 48.60
1	Rear end panel <i>517</i>
1	Rear end panel garnish <i>160.50</i>
1	Rear exhaust silencer
1	Rear exhaust insulator
2	Rear exhaust mountings @ 28.20
1	Rear floor board
1	Rear floor sponge tray
1	Rear floor panel
1	Rear floor panel undercover
2	Rear fender protectors - L/R @ 341.60
1	Rear smart keyless antenna <i>85.20</i>
1	Rear smart keyless buzzer

	Amount \$	
B	1,287.10	✓
na	121.60	✓
Pa	391.40	X
na	48.80	X
na	68.80	✓
na	68.80	✓
Pa	820.40	X
nd	281.30	✓
Pa	481.60	X
Pa	86.90	X
nd	210.20	<i>502.00 8420</i>
Pa	372.20	X
Pa	25.20	X
Pa	976.20	X
B	791.60	✓
Pa	179.80	X
Pa	482.40	X
Pa	97.20	X
B	659.10	✓
my	211.60	✓
Pa	576.50	X
Pa	120.30	X
Pa	56.40	X
Pa	370.60	X
Pa	321.60	X
Pa	871.90	X
Pa	286.90	X
Pa	683.20	X
cm	191.20	✓
Pa	199.60	X

Sub-total 11,340.40
 Less 20% 2,268.08
 Total List 9,072.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to first approval from Insurance Company

Page 1 of 2

Acknowledged by Repairer

Signature:

Date:

Vehicle number: SLM2853G

Vehicle Make & Model: HONDA HRV

Special Nett Items

1 set Tailgate glass sealant
1 set Tailgate outer garnish clip
1 set Rear bumper clip
1 set Rear no. plate
1 Rear reverse camera
1 set Rear reverse sensor - 4 Pcs

<i>nn</i>	80.00	<i>405AL</i>
<i>nn</i>	80.00	<i>X</i>
<i>nn</i>	50.00	<i>✓</i>
<i>SL</i>	60.00	<i>X</i>
<i>P2</i>	450.00	<i>X</i>
<i>odd short</i>	480.00	<i>✓ 20052</i>
Total Special Nett	1,200.00	

Labour charges

To check rear electrical wiring
To remove, refix tailgate glass
Transfer & reinstall tailgate components to new tailgate
To remove, refix rear interior trims to assist repair
To remove, refix rear reverse sensor / camera
To remove, refix rear exhaust
To respray undercoating
To respray painting and etc
Panel beating, cut, weld remove & replacing above parts

	50.00	<i>201</i>
	180.00	<i>1201</i>
	150.00	<i>601</i>
	120.00	<i>801</i>
	80.00	<i>602</i>
<i>nn</i>	80.00	<i>X</i>
	120.00	<i>601</i>
	1,200.00	<i>6001</i>
	1,400.00	<i>8001</i>
Total Labour	3,380.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 13,652.32