

D&K AUTOMOTIVE SERVICES PTE LTD

BLK C KAI BUKIT AVE 6 #01-59 SINGAPORE 417883

Vehicle No : GBE7924M
Chassis No : JJTFAT35Y90K206103

Make & Model : TOYOTA DYNA 15
DOA : 18/06/2024

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	Front corner panel RH <i>new</i>	1	\$ 680.00	\$ 680.00
2	Front side mirror garnish <i>new</i>	1	\$ 430.00	\$ 430.00
3	Front side mirror RH <i>Missing</i>	1	\$ 285.00	\$ 285.00
4	Front side mirror arm RH <i>new</i>	1	\$ 585.00	\$ 585.00
5	Front door RH <i>Dented</i>	1	\$ 2,250.00	\$ 2,250.00
6	Front door inner trim RH <i>new</i>	1	\$ 750.00	\$ 750.00
7	Front door inner trim board speaker RH <i>new</i>	1	\$ 325.00	\$ 325.00
8	Front door outer glass moulding RH <i>new</i>	1	\$ 289.00	\$ 289.00
9	Front door outer glass weathership RH <i>new</i>	1	\$ 450.00	\$ 450.00
10	Front door outer handle RH <i>new</i>	1	\$ 225.00	\$ 225.00
11	Front door glass RH <i>new</i>	1	\$ 890.00	\$ 890.00
12	Front door step garnish RH <i>new</i>	1	\$ 350.00	\$ 350.00
13	Front door step panel RH <i>new</i>	1	\$ 525.00	\$ 525.00
14	Front door weatherstrip RH <i>new</i>	1	\$ 202.00	\$ 202.00

TOTAL PRICE \$ 7,556.00
LESS 25% **-\$ 1,889.00**
SUB TOTAL PRICE \$ 5,667.00

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	Front door step garnish clips <i>new</i>	10	\$ 50.00	\$ 50.00
2	Front door inner trim board clips <i>new</i>	10	\$ 50.00	\$ 50.00
3	Register company sticker <i>new</i>	1	\$ 100.00	\$ 100.00

TOTAL \$ 200.00

CLAIM DETAILS: LABOUR

S/N	JOB DESCRIPTION	Work Unit	APPROVED
1	Knocking adjust side on affected areas.	200x1day	\$ 1,000.00
2	To putty, re-spray painting and polish side affected areas.	200x1area	\$ 1,000.00
3	To rust proof affected side areas.		\$ 100.00

4	To check wiring and rectify front.		\$	100.00	30
5	To remove and transfer front door assy in order to works.		\$	200.00	40
6	To remove and refit front door glass assy.		\$	100.00	40

TOTAL

\$ 2,500.00

ESTIMATE REPORT

NOTE: ALL QUOTED PRICE IS SUBJECT TO 9% GST

TOTAL PARTS COST : \$ 5,867.00
TOTAL LABOUR COST : \$ 2,500.00
TOTAL REPAIR COST : \$ 8,367.00

Adnan S
2/8 24/06/24.
038yp

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: