Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited From: LKK Auto Consultants Pte Ltd

10 Eunos Road 851 Ubi Ave 1 #01-25#09-04A Singapore Post CentrePaya Ubi Industrial ParkSingapore 408600Singapore 408933

Attn: Sharon Tan Chow Yen Date: 24 Sep 2024

Preliminary Advice

Vehicle No : SML1665H Accident Date : 18/09/2024

Make : BMW 316I Policy No. : MPC23P00248600

Assignment Date : 20/09/2024 Excess : \$\$500.00

Date of Inspection : 23/09/2024 Est. Duration of Repair : 0

Inspection At : VERVE MOTORCLINIC PTE LTD (KAKI BUKIT)

NO. 25 KAKI BUKIT ROAD 4, #03-39 SYNERGY@KB

SINGAPORE 417800

Point of Impact / General Description of Damages

The vehicle caught fire. Pending for investigation

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS

Check Items (Estimated) :S\$
Total :S\$

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$
 72,000.00

 COE / PARF Rebate
 :S\$
 33,024.00

Salvage Value :S\$

Margin for Repair :S\$ 38,976.00

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	IJ
		let us have your authorisation.	

(X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: PENDING FOR INVESTIGATION.