



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24090381/Uvh3
75 BRAS BASAH ROAD	Date:	04/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLU 2426P	Veh. Inspected	SLS 9698K
Policy No.	-	Coverage	0
Claim No.	MT/1296084-001	Excess	\$0.00
Assign From	JULIE	Assign Date	20/09/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ E250 (A)	C.C	1991
Engine No.	27492031168428	Year of Reg.	21/11/2017
Chassis No.	WDD2130452A324180	Colour	SILVER
Odometer	150883 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/45R18	CONTIENETAL	6
L/H Front Tyre	245/45R18	CONTIENETAL	6
R/H Rear Tyre	245/45R18	CONTIENETAL	6
L/H Rear Tyre	245/45R18	CONTIENETAL	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/09/2024	Inspection Date	23/09/2024 (12:35)
Survey held at	HONG AUTO SERVICES 2 KAKI BUKIT AVENUE 2 #01-28 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days