

HONG AUTO SERVICES

2 Kaki Bukit Ave 2, #01-28, Singapore 417921
 Tel: 6747 6436 / Fax: 6746 8868 / HP: 9853 5155
 Email: tchong4281@gmail.com

Not Authorized
 M
 meru
 23/9/24
 3 days
 4/5 & 5500
 Total plus Allowance

Vehicle number: SLS9698K

Vehicle Made & Model: MERCEDES-BENZ E250

Qty	List Items		Amount \$
1	Front bumper	1874.44	1,989.61 ✓
1	Front bumper PDC sensor - RH		283.55 X
1	Front bumper side grille - RH		102.63 X
1	Front bumper top seal		110.20 X
1	Front bumper side bracket - RH		89.95 X
1	Front fender - RH		1,042.16 X
1	Front fender inner shield		141.52 X
1	Front headlamp - RH		3,968.21 ✓
1	Front sport wheel - RH		1,655.90 ✓ 800 s/w
1	Front knuckle arm - RH		1,210.43 X
1	Front wheel hub bearing		599.61 X
1	Front lower control arm		561.20 X
Sub-total			11,754.97
Less 10%			1,175.50
Total List			10,579.47

Special Nett Items

1 set	Front bumper clip		60.00 40 s/w
Total Special Nett			60.00

Labour Charges

To check front electrical wiring	50.00	20
To remove, refix front undercarriage	250.00	X
To check wheel alignment	120.00	60
To respray painting & etc	800.00	300
Panel beating, cut, weld, remove & replacing above parts	800.00	400
Total Labour	2,020.00	

ESTIMATE PARTS & LABOUR GRAND TOTAL \$

12,659.47

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 1

Acknowledged by Repairer
 Signature:
 Date:

P- 5861 65
 102
 525839
 800
 780
 587839
 202
 5502