



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925
	Document No. 0	
	Document Date 23/09/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	30/06/2017	SLQ2249E	0	33202	75/DS/SLQ2249E

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU603561848	2ZRS057165	60	Ng Mei Yen	--/--	0.00 --/-- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	B	BP-LAB2 CHECK WIRING SYSTEM				198.00
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
3	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				198.00
4	B	BP-LAB2 REMOVE INTERIOR UPSTOPY TO FAC REPAIR				792.00
5	B	BP-LAB2 REMOVE AND TRANSFER REAR & FRONT DOOR CO MPARTMENT				792.00
6	B	BP-MECH2 CONDUCT WHEEL ALIGHTMENT				198.00
7	B	BP-LAB2 REPL ACC AFF AREA				198.00
		STRAIGHTEN AND PANEL BEAT ACC AFF AREA				4752.00
8	B	BP-RES2 RESPRAY ACC AFF AREA				5248.00
9	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR				
		TP VEH NO.: SMRT BUS ACC DATE:21/09/24				
		DRIVE IN:21/09/24				
		DATE SURVEY:				
		NO OF REPAIR DAYS:				
		BY: AUTHORISED ON:				
10	1	U52158-47913 COVER, RR BUMPER	1.00	680.60		680.60
11	2	U52576-47040 RETAINER, RR BUMPER	1.00	177.50		177.50
12	3	U52592-47040 SEAL, RR BUMPER	1.00	122.30		122.30
13	4	U52453-47010 GUARD, RR BUMPER,	1.00	884.60		884.60

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925
	Document No. 0	
	Document Date 23/09/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	30/06/2017	SLQ2249E	0	33202	75/DS/SLQ2249E
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKB3FU603561848	2ZRS057165	60	Ng Mei Yen	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	5	U52566-47900 FILLER, RR BUMPER <i>XAN</i>	1.00	170.50		170.50
15	6	K52161-0K040 PIECE, RR BUMPER <i>XAN</i>	10.00	5.80		58.00
16	7	U61602-47160 PANEL SUB-ASSY, <i>repair</i>	1.00	1339.40		1339.40
17	8	U58746-47030 PROTECTOR, QUARTER <i>XAN</i>	1.00	31.90		31.90
18	9	T08826-08115 PANEL BONDING AD <i>XAN</i>	1.00	267.20		267.20
19	0	U67004-47211 PANEL SUB-ASSY, RR <i>repair</i>	1.00	1988.60		1988.60
20	1	U67872-47051 WEATHERSTRIP, RR <i>XAN</i>	1.00	249.10		249.10
21	2	U75978-47080 STRIPE, RR DOOR, <i>XAN</i>	1.00	30.40		30.40
22	3	U75988-47060 STRIPE, RR DOOR, <i>XAN</i>	1.00	48.50		48.50
23	4	U75989-47070 STRIPE, RR DOOR, <i>XAN</i>	1.00	21.40		21.40
24	5	U67002-47163 PANEL SUB-ASSY, FR <i>repair</i>	1.00	1996.10		1996.10
25	6	U67862-47050 WEATHERSTRIP, FR <i>XAN</i>	1.00	320.90		320.90
26	7	U75976-47060 STRIPE, FR DOOR, <i>XAN</i>	1.00	18.50		18.50
27	8	U75986-47050 STRIPE, FR DOOR, <i>XAN</i>	1.00	60.40		60.40
28	9	U75966-47030 STRIPE, FR DOOR <i>XAN</i>	1.00	36.60		36.60
29	0	L90269-04051 RIVET <i>XAN</i>	20.00	2.20		44.00
30	1	T90269-06013 RIVET <i>XAN</i>	20.00	2.80		56.00
31	2	U53802-47100 FENDER SUB-ASSY, FR <i>bt</i>	1.00	1488.90		1488.90
32	3	U53828-47070 PROTECTOR, FR FENDER <i>XAN</i>	1.00	129.90		129.90
33	4	U53808-47020 SEAL SUB-ASSY, <i>XAN</i>	1.00	72.00		72.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	

Customer Copy

Borneo Motors

Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. 6631 1188



ESTIMATE

Account Details			Customer Details				
THIRD PARTY CLAIM	Account No.	M/S Grab Rentals Pte. Ltd					
	S1000020 / TPCLAIM	3 Media Close					
	Document No.	#01-03/06					
	0	Singapore 138498					
	Document Date	Work: 65703925					
	23/09/2024						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	30/06/2017	SLQ2249E	0	33202	75/DS/SLQ2249E
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKB3FU603561848	2ZRS057165	60	Ng Mei Yen	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
34	5	U53155-47010 SEAL, RADIATOR ?Xan	1.00	58.30		58.30	
35	6	U53876-47110 LINER, FR FENDER, LH de	1.00	308.70		✓ 308.70	
36	7	U52119-47962 COVER, FR BUMPER repair	1.00	799.30		799.30	
37	8	K52161-0K040 PIECE, RR BUMPER	10.00	5.80		✓ 58.00	
38	9	U52115-47050 SUPPORT, FR BUMPER Xan	1.00	121.30		✓ 121.30	
39	0	U52116-47050 SUPPORT, FR BUMPER Xan	1.00	121.30		121.30	
40	1	U53112-47240 GRILLE, RADIATOR, Xan	1.00	237.60		237.60	
41	2	U81145-47691 UNIT, HEADLAMP Xan	1.00	4063.00		4063.00	
42	3	U81145-47691 UNIT, HEADLAMP ?Xan	1.00	4063.00		4063.00	
43	4	U81220-47020 LAMP ASSY, FOG, LH Xan	1.00	1449.90		1449.90	
44	5	U75374-47150 EMBLEM, SIDE PANEL	1.00	75.70		✓ 75.70	
45	6	U42602-47181 CAP SUB-ASSY, WHEEL scan	2.00	293.60		✓ 587.20	
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis							
For & on behalf of Borneo Motors (Singapore) Pte Ltd Signature: _____ Date: _____			Customer's Signature Signature: _____ Date: _____		Charge Summary Parts 22,236.60 Labour 12,376.00 Sublet 0.00 Lubrication/Fluid 0.00 Others 0.00		
Total 34,612.60 GST 9.00% 3,115.11 Less 0.00 Amount Due 37,727.71							

Customer Copy