

Vehicle number	SLE7342Z
Make / Model	VOLKSWAGEN JETTA
Chassis number	WVWZZZ16ZGM017896
Accident date	19/9/24
Reference	2409-19

Qty	Particulars	Unit Price - SGD \$	
PARTS REPLACEMENT - LIST ITEMS			
1	REAR BUMPER <i>BR</i>	1450.00	1366.35 ✓
1	REAR BUMPER RETAINER <i>BR</i>	158.00	✓
1	REAR FENDER RH <i>X R</i>	1758.05	
1	REAR FENDER INNER SHIELD RH <i>X nn</i>	179.75	
1	REAR LOWER ARM RH <i>X nn</i>	470.20	
1	REAR KNUCKLE ARM RH <i>BT</i>	818.15	689 ✓
1	REAR KNUCKLE ARM BEARING RH <i>RC</i>	452.30	323 ✓
1	REAR SHOCK ABSORBER RHJ <i>X nn</i>	309.25	
		5595.70	2536.35
	Less 10%	559.57	-10%
		5036.13	2282.71
PARTS REPLACEMENT - SPECIAL NETT ITEMS			
1 SET	REAR BUMPER CLIP <i>q - RC</i>	30.00	✓
1	REAR RIM RH <i>UT</i>	750.00	500
	Subtotal	780.00	530
	Balance C/F	5816.13	
LABOUR AND MISCELLANEOUS CHARGES			
1	CHECK WIRING AND LIGHTNING SYSTEM	150.00	30
2	REMOVE & REPLACE REAR BUMPER SENSOR	150.00	30
3	COMPUTERIZE AND CHECK WHEEL ALIGNMENT	200.00	80
4	REMOVE AND REPLACE REAR UNDERCARRIAGE	200.00	100
5	PANEL BEATING ON AFFECTED AREAS	800.00	200
6	SPRAY PAINTING ON AFFECTED AREAS	800.00	400
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00	30
	Subtotal	2450.00	870
	Grand total	8266.13	

Steve (LKK)
25/9/24, 12.00pm

W R
L/S
M AL My
4 djs

3682.71

L/S - 2946.16
= 2950

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: