

Performance Motors

BMW Dealer



Final Report

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function

177.00

177.00

Sundries

150.00

150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
V BAND CLAMP <i>ne</i> ✓	47.55	1.00	0.00	47.55
# CLAMPING BUSH <i>ne</i> ✓	76.05	2.00	0.00	152.10
# GASKET RING <i>ne</i> ✓	33.25	1.00	0.00	33.25
V BAND CLAMP <i>ne</i> ✓	47.55	1.00	0.00	47.55
# LH TAILPIPE TRIM CHROME <i>bt</i> ✓	206.65	1.00	0.00	206.65
# RH TAILPIPE TRIM CHROME	206.65	1.00	0.00	206.65
# REAR SILENCER BRACKET FRT <i>ca</i> ✓	66.55	2.00	0.00	133.10
# SWING SUPPORT <i>bt</i> ✓	49.95	1.00	0.00	49.95
# REAR SILENCER WITH EXHAUST FLAP	2,756.40	1.00	0.00	2,756.40
# INTERMEDIATE PIPE	682.65	1.00	0.00	682.65
# RP PETROL PARTICULATE FILTER W/FR. <i>bt</i> ✓	3,510.50	1.00	0.00	3,510.50
# RP CATALYTIC CONVERTER NEAR ENGINE <i>bt</i> ✓	3,145.30	1.00	0.00	3,145.30
# REAR BUMPER CARRIER	633.60	1.00	0.00	633.60
REAR BUMPER TRIM STRIP	49.35	1.00	0.00	49.35
REAR BUMPER BOTTOM TRIM PANEL	329.90	1.00	0.00	329.90
REAR CENTRE GUIDE	189.85	1.00	0.00	189.85
REAR BUMPER BOTTOM REINFORCEMENT	177.55	1.00	0.00	177.55
REAR BUMPER TRIM PANEL (PDC/PMA)	1,731.95	1.00	0.00	1,731.95
# UNDERBODY PANELLING REAR <i>st</i> ✓	52.70	1.00	0.00	52.70
REAR RH REAR REFLECTOR	45.70	1.00	0.00	45.70

SUPPLEMENTARY ITEMS

Total Labour :	9,490.00
Total Parts :	14,182.25
Total Labour & Parts (before GST) :	23,672.25
Deduction for Excess :	
Total Repair Costs less Excess:	23,672.25 ✓
GST @9%:	2,130.50
Grand Total :	25,802.75