

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SMV9577Z

Make & Model: Toyota Voxy Hybrid

Chassis number: ZWR800404189

No.	Description of spare parts	Qty	Amount S\$
1	Bonnet <i>Dented</i>	1	\$ 1,093.20
2	Bonnet lock <i>sw</i>	1	\$ 295.40
3	Bonnet RH hinge } <i>Bent</i>	1	\$ 88.90
4	Bonnet LH hinge }	1	\$ 88.90
5	Bonnet inner heat insulator <i>Yellow</i>	1	\$ 453.20
6	Bonnet inner heat insulator clips <i>Yellow</i>	1set	\$ 80.00
7	Front bumper (painted) <i>Dented</i>	1	\$ 1,593.10
8	Front bumper clips <i>sw</i>	1set	\$ 70.00
9	Front bumper LH fog lamp <i>Gold</i>	1	\$ 412.90
10	Front bumper LH fog lamp cover <i>Gold</i>	1	\$ 157.80
11	Front bumper LH fog lamp cover chrome <i>sw</i>	1	\$ 202.50
12	Front bumper RH centre PDC sensor <i>new</i>	1	\$ 368.90
13	Front bumper LH centre PDC sensor <i>Misaligned</i>	1	\$ 368.90
14	Front bumper LH side PDC sensor <i>new</i>	1	\$ 368.90
15	Front bumper lower grille <i>new</i>	1	\$ 178.60
16	Front bumper inner sponge <i>embled</i>	1	\$ 231.40
17	Front bumper reinforcement <i>Dented</i>	1	\$ 581.90
18	Front bumper reinforcement LH bracket <i>new</i>	1	\$ 67.80
19	Front bumper LH retainer <i>Gold</i>	1	\$ 170.85
20	Front bumper RH retainer <i>sw</i>	1	\$ 170.85
21	Front bumper under cover <i>new</i>	1	\$ 132.90
22	LH headlamp assy <i>embled</i>	1	\$ 4,505.60
23	LH headlamp garnish <i>new</i>	1	\$ 215.50
24	Front chrome grille <i>embled</i>	1	\$ 860.70
25	Front chrome grille emblem <i>sw</i>	1	\$ 116.20
26	Front chrome grille clips <i>sw</i>	1set	\$ 60.00
27	Support panel <i>embled</i>	1	\$ 2,259.10
28	Support panel upper cover <i>Gold</i>	1	\$ 311.20
29	Support panel upper cover clips <i>sw</i>	1set	\$ 70.00
30	Aircon condenser <i>new</i>	1	\$ 1,899.30
31	Radiator assy <i>embled</i>	1	\$ 2,203.10
32	Front LH fender <i>embled</i>	1	\$ 903.10
33	Front LH fender "Hybrid" emblem <i>sw</i>	1	\$ 98.00
34	Front LH fender splash shield <i>Gold</i>	1	\$ 244.60
35	Front LH fender splash shield clips <i>sw</i>	1set	\$ 70.00

✓
 +
 ✓
 ✓
 +
 +
 1050.
 30.
 +
 +
 +
 +
 +
 260
 260
 +
 ✓
 - 371
 +
 +
 +
 +
 3384
 +
 ✓
 ✓
 20945
 +
 ✓
 ✓
 +
 +

\$ 20,993.30
 Parts less 25% \$ 5,248.33
 Total: \$ 15,744.98

No.	Special Nett Items	Qty	Amount S\$
1	Front number plate <i>mn</i>	1	\$ 80.00 <i>+</i>
2	Radiator coolant <i>lu</i>	1	\$ 70.00 <i>50</i>

Total: \$ 150.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,500.00 <i>800</i>
2	Spray painting on affected areas and panels	\$ 1,400.00 <i>1000</i>
3	Check wiring and lighting system on affected areas	\$ 70.00 <i>30</i>
4	Apply rust coating chemical on affected areas and panels	\$ 70.00 <i>50</i>
5	Remove and replace front bumper PDC sensors to assist repair	\$ 120.00 <i>50</i>
6	Remove and replace aircon condenser and pipes to assist repair	\$ 220.00 <i>60</i>
7	Remove and replace radiator assy, pipes and hoses to assist repair	\$ 220.00 <i>60</i>

Total: \$ 2,100.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 15,744.98
 Special Nett: \$ 150.00
 Labour: \$ 2,100.00
 Total: \$ 17,994.98

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

Adrian G
L/S 24/09/24
07 Days

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
 #01-49 SINGAPORE 415875
 Tel: +65 64524457
 Fax: +65 64524584

Parts prices revised

Vehicle number: SMV9577Z
 Make & Model: Toyota Voxy hybrid

Date of survey:
 Name of surveyor:
 Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bonnet chrome <i>chrome</i>	1	\$ 637.00
2	RH headlamp <i>chrome</i>	1	\$ 4,609.00

← 326
 3384

\$ 5,246.00
 Parts less 25% \$ 1,049.20
 Total \$ 4,196.80

No.	Special Nett Items	Qty	Amount S\$

Total: \$ _____

No.	Labour and painting	Amount S\$

Total: \$ _____

Agreed Amount: _____ (Part by Part / Lump sum)
 Working days: _____

Admin L
SPS

Spare Parts: \$ 4,196.80
 Special Nett: \$ -
 Labour: \$ -
Total Amount: \$ 4,196.80