

TICK HAI MOTOR & WELDING SERVICES
1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 48992400W

*Not Authorized
 all
 morais
 24/9/24
 2/5 \$10,400
 take photo after 18 days
 7 days*

Vehicle Number: SLZ9779Z
Vehicle Model : Toyota Vios E(Auto)
Manufacturing Year : 2018
Chassis : MR2B23F3401116097

S/N.	Item Description	Amount (\$)
1	Headlamp (LH) 1698.01 CNE	\$ 2,090.18
2	Front Bumper 688.50 24/7/11	\$ 1,241.81
3	Front Bumper Side Retainer (LH) 500	\$ 169.44
4	Front Bumper Clip x 1 Set 100	\$ 50.00
5	Front Fender (LH) 980.20 400/20	\$ 1,066.92
6	Front Fender Side Panel Protector (LH) 100	\$ 189.32
7	Front Fender Inner Garnish (LH) 288.50 70/11	\$ 338.40
8	Front Fender Inner Garnish Clip x 1 set 100	\$ 50.00
9	Front Fender Triangle Black Garnish (LH) 100	\$ 132.76
10	Side Mirror Assy (LH) 100	\$ 662.95
11	Front Door (LH) 300/20	\$ 1,460.95
12	Front Door Hinge (LH) x 2 pcs 300	\$ 166.26
13	Front Door Checker (LH) 100	\$ 153.98
14	Front Door Weatherstrip (LH) 188.50 100	\$ 399.07
15	Front Door Inner Lock (LH) 500	\$ 753.81
16	Front Door Regulator (LH) 300	\$ 620.98
17	Front Door Lock Catch (LH) 100	\$ 50.92
18	Front Door Inner Trimboard (LH) 300.80 24/7/11	\$ 1,050.30
19	Front Door Inner Trimboard Clip x 1 set 100	\$ 50.00
20	Front Door Window Black Sticker 80 100	\$ 114.61
21	Front Door Window Outer Black Moulding (Centre) 100	\$ 101.73
22	Front Door Frame Weatherstrip (LH) 100	\$ 442.23
23	Rear Door (LH) 100	\$ 1,559.61
24	Rear Door Hinge (LH) x 2 pcs 300	\$ 159.93
25	Rear Door Checker (LH) 500	\$ 153.98
26	Rear Door Weatherstrip (LH) 188.50 100	\$ 363.72
27	Rear Door Inner Lock (LH) 400	\$ 440.30
28	Rear Door Regulator (LH) 300	\$ 533.38
29	Rear Door Lock Catch (LH) 100	\$ 50.92
30	Rear Door Inner Trimboard (LH) 870.50 24/7/11	\$ 1,050.30
31	Rear Door Inner Trimboard Clip x 1 set 100	\$ 50.00

11231.66

32	Rear Door Window Black Sticker	80 per	\$	114.61	/
33	Rear Door Window Outer Moulding (Bottom)	NS	\$	99.43	X
34	Rear Door Window Outer Black Moulding (Centre)	Suf	\$	101.73	/
35	Rear Door Frame Weatherstrip (LH)	11	\$	470.20	X
36	Door Centre Pillar (LH)	R	\$	885.61	X
37	Door Centre Pillar Black Sticker	11	\$	114.61	X
38	Rocker Panel (LH)	680.80 1-400	\$	848.23	/
39	Front Shock Absorber (LH)	Suf	\$	688.52	X
40	Front Lower Arm (LH)	Suf	\$	701.13	/
41	Front Knuckle (LH)	Suf	\$	586.08	/
42	Front Wheel Hub (LH)	385.00 Dyle	\$	528.84	/
Total :			\$	20,857.75	
Less 25% :			\$	5,214.44	
Amount :			\$	15,643.31	

Labour	Amount (\$)
To conduct 4-wheel alignment	\$ 80.00
To check front electrical wiring system and focus headlamp	\$ 80.00
To remove & install LHF rim and conduct tyre balancing	\$ 80.00
To remove & install LHF undercarriages	\$ 280.00
To transfer LHF door components from old door to new door	\$ 150.00
To transfer LHR door components from old door to new door	\$ 150.00
To remove interior garnishes and trims etc to facilitate repair	\$ 150.00
To apply anti-rusting coating on new and affected panels	\$ 200.00
To remove, replace above listed parts and panel, straighten and panel beat accident affected areas	\$ 1,800.00
To spray painting on affected areas	\$ 1,800.00
LKK Auto Consultants hence notify the Repairer of the following:	Labour Total : \$ 4,770.00
	Total (Parts & Labour) \$ 21,263.31

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date:

$$\begin{array}{r} 2-13766.40 \\ 252 \\ \hline 10324.80 \\ 400 \\ 2350 \\ \hline 13074.80 \\ 202 \\ \hline 10459 \end{array}$$