

(08/11/13) wef

REF:

CS/FCI 24090394/Urps3

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SL297792at Workshop m/s 7.ck he

of _____

Insured: SMA 3007L

Policy No. _____

Claims No. D24008252MFCT

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: 853k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No**CA / REV / REP. / 24 HRS**Date: _____ Person Contacted: 4686

Vehicle: IN / OUT

Veh No: SL2 97792 Yr Regn: 26/03/18Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**Truck / Trailer or (A)Make: Toyota Vios E c.c. 1496Colour: Red A/C: **Insured / Std / NI / NA**Sp. Reading: 134042 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: MR2B23F3401116097Gen. Cond: **Good / Fair / Poor / Burnt**Steering: ~~Inorder~~ / ~~Jammed~~ / ~~Leaked~~ / ~~Burnt~~ or affectedBrake: ~~Inorder~~ / ~~Jammed~~ / ~~Leaked~~ / ~~Burnt~~ or _____Modi: **Nil / S/Rim / STD A/Rim** or _____Tyre Size: **F:** 185/60R15**R:** _____**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /****TOYO / YOKO** or _____Front: _____ Rear: 6R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 18/09/24 D.O.I. 24/9/24

Survey held at _____

Des. of Damages: **Fit / Rear / O/S / N/S / U/C / Rooftop** orMS bodyThe **U/C / Chassis frame / Body Structure** affected due to collision.Date / Time Action / Instruction 24/13k9/10/24 2/5 @ 10.400 informed Robert (red 10,863.31, 51%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	468B
Vehicle Details	
Vehicle No.:	SLZ9779Z
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2024
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2NR5207974
Chassis No.:	MR2B23F3401116097
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,707.00
Original Registration Date:	26 Mar 2018
First Registration Date:	26 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$13,707.00 6817
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Mar 2028
PARF Rebate Amount:	\$8,909.00
Intended COE Rebate Details	
COE Expiry Date:	25 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,890.00
COE Rebate Amount:	\$12,921.00
Total Rebate Amount:	\$21,830.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 24 Sep 2024

OK



All Category

Filter

Search



Save Search



2018 X

19 Vehicles

Car Make

Car Model

Price Range

Depreciation

2018

Mil

Toyota Vios
1.5A G

\$56,888

Instl. \$1,078

/mth

\$14,070 /yr

1,496 cc

20-Mar-2018

(3yrs 5mths COE left)

70,637 km

3 Owners

Priced to sell. This is the higher end "g" model specifications unit. Genuine low mileage, fully maintained by Toyota agent Borneo Motors! Well taken care of by previous owner. In-house motul garage service package available. Hassle free trade-in & financing available.

Posted 23-Sep-2024

☐ Compare

PREMIUM AD

Toyota Vios
1.5A E

\$60,800

Instl. \$1,055

/mth

\$14,400 /yr

1,496 cc

27-Jun-2018

(3yrs 9mths COE left)

113,000 km


1 Owner

Newly arrived! Cheapest and best condition in market! High specs E model plus superb fuel efficiency of 17.2km/l. View to believe. No major repairs needed.

Ka-Hup Vehicles Trading|Posted 23-Sep-2024

☐ Compare

PREMIUM AD

Toyota Vios
1.5A G

\$62,800

Instl. \$1,026

/mth

\$13,680 /yr

1,496 cc

08-Oct-2018

(4yrs COE left)

70,000 km

1 Owner

Pristine condition 1 owner unit. Very reliable and fuel efficient Vios needs no further introduction. We offer financing to cater to your needs, contact us today to find out more about this unit!

Posted 23-Sep-2024

☐ Compare

PREMIUM AD

Compare

TICK HAI MOTOR & WELDING SERVICES
1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 48992400W

*Not Authorized
 24/9/24
 2/5 \$10,400/
 take photo after 18 days
 7 days*

Vehicle Number: SLZ9779Z
Vehicle Model : Toyota Vios E(Auto)
Manufacturing Year : 2018
Chassis : MR2B23F3401116097

S/N.	Item Description	Amount (\$)
1	Headlamp (LH) 1698.01 CNE	\$ 2,090.18
2	Front Bumper 688.50 24/7/11	\$ 1,241.81
3	Front Bumper Side Retainer (LH) 500	\$ 169.44
4	Front Bumper Clip x 1 Set 100	\$ 50.00
5	Front Fender (LH) 980.20 404/20	\$ 1,066.92
6	Front Fender Side Panel Protector (LH) 100	\$ 189.32
7	Front Fender Inner Garnish (LH) 288.50 70/11	\$ 338.40
8	Front Fender Inner Garnish Clip x 1 set 100	\$ 50.00
9	Front Fender Triangle Black Garnish (LH) 100	\$ 132.76
10	Side Mirror Assy (LH) 100	\$ 662.95
11	Front Door (LH) 304/20	\$ 1,460.95
12	Front Door Hinge (LH) x 2 pcs 300	\$ 166.26
13	Front Door Checker (LH) 700	\$ 153.98
14	Front Door Weatherstrip (LH) 188.50 70/11	\$ 399.07
15	Front Door Inner Lock (LH) 500	\$ 753.81
16	Front Door Regulator (LH) 300	\$ 620.98
17	Front Door Lock Catch (LH) 100	\$ 50.92
18	Front Door Inner Trimboard (LH) 900.80 24/7/11	\$ 1,050.30
19	Front Door Inner Trimboard Clip x 1 set 100	\$ 50.00
20	Front Door Window Black Sticker 80 100	\$ 114.61
21	Front Door Window Outer Black Moulding (Centre) 100	\$ 101.73
22	Front Door Frame Weatherstrip (LH) 100	\$ 442.23
23	Rear Door (LH) 100	\$ 1,559.61
24	Rear Door Hinge (LH) x 2 pcs 300	\$ 159.93
25	Rear Door Checker (LH) 500	\$ 153.98
26	Rear Door Weatherstrip (LH) 188.50 70/11	\$ 363.72
27	Rear Door Inner Lock (LH) 400	\$ 440.30
28	Rear Door Regulator (LH) 300	\$ 533.38
29	Rear Door Lock Catch (LH) 100	\$ 50.92
30	Rear Door Inner Trimboard (LH) 890.50 24/7/11	\$ 1,050.30
31	Rear Door Inner Trimboard Clip x 1 set 100	\$ 50.00

11231.66

32	Rear Door Window Black Sticker	80 per	\$	114.61	✓
33	Rear Door Window Outer Moulding (Bottom)	NS	\$	99.43	X
34	Rear Door Window Outer Black Moulding (Centre)	Surf	\$	101.73	✓
35	Rear Door Frame Weatherstrip (LH)	11	\$	470.20	X
36	Door Centre Pillar (LH)	12	\$	885.61	X
37	Door Centre Pillar Black Sticker	111	\$	114.61	X
38	Rocker Panel (LH)	680.80 1-400	\$	848.23	✓
39	Front Shock Absorber (LH)	Surf	\$	688.52	X
40	Front Lower Arm (LH)	Surf	\$	701.13	✓
41	Front Knuckle (LH)	Surf	\$	586.08	✓
42	Front Wheel Hub (LH)	385.00 2-400	\$	528.84	✓
Total :			\$	20,857.75	
Less 25% :			\$	5,214.44	
Amount :			\$	15,643.31	

S/N	Special Nett Items	Amount (\$)
1	Front Tyre Rim (RH)	\$ 850.00
Amount :		\$ 850.00

Labour	Amount (\$)
To conduct 4-wheel alignment	\$ 80.00
To check front electrical wiring system and focus headlamp	\$ 80.00
To remove & install LHF rim and conduct tyre balancing	\$ 11 80.00
To remove & install LHF undercarriages	\$ 280.00
To transfer LHF door components from old door to new door	\$ 150.00
To transfer LHR door components from old door to new door	\$ 150.00
To remove interior garnishes and trims etc to facilitate repair	\$ 150.00
To apply anti-rusting coating on new and affected panels	\$ 200.00
To remove, replace above listed parts and panel, straighten and panel beat accident affected areas	\$ 1,800.00
To spray painting on affected areas	\$ 1,800.00
LKK Auto Consultants hence notify the Repairer of the following:	Labour Total : \$ 4,770.00
• To resurvey before/after spray painting	Total (Parts & Labour) \$ 21,263.31

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer


Signature:

Date:

2-13766.40
252
10324.80
400
2350
13074.80
202
10459.



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	TICK HAI	DATE	Sep 24, 2024 10:18:28 AM
FIRST NAME			
LICENSE NO.	SLZ 9779 Z		
MILEAGE	134046		
MAKE	CUSTOM	MODEL	TOYOTA VIOS (P151)
NOTES			

Front Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.00	0.00	1.00			-7.30				-7.30		
PARTIAL TOE	-0.50	0.00	0.50		-4.40		-2.90		-7.60		0.20	
SET BACK	---	---	---			-0°48"				-0°48"		
CAMBER	-0°58"	-0°12"	0°30"		-1°20"		-0°20" 1°00"		-1°20"		-0°24" 0°56"	
CASTER	3°06"	4°06"	5°06"		4°16"		4°38" 0°20"		4°16"		4°38" 0°20"	
KING-PIN	---	---	---		10°54"		10°28" 0°26"		10°54"		10°28" 0°26"	
INCL. ANGLE	---	---	---		9°34"		10°08"		9°34"		10°04"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	---	---	---			3.40				3.40		
PARTIAL TOE	---	---	---		2.50		0.90		2.50		0.90	
SET BACK	---	---	---			0°04"				0°04"		
CAMBER	---	---	---		-0°44"		-0°44" 0°00"		-0°44"		-0°44" 0°00"	
THRUST ANGLE	---	---	---			0°06"				0°06"		