

CHOO MOTOR SPRAY PAINTER  
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY  
SINGAPORE 417883

NOT Authorised  
mruy  
24/9/24  
2/5 \$5000  
Chap. H. H. H.  
4 days.

VEHICLE No: SLC 6845G

1PC	REAR WINDSCREEN MOULDING	nee		\$110.20	
1PC	TAILGATE	12/3ent		\$1,099.20	
1PC	TAILGATE 'VEZEL' EMBLEM	nee		\$66.80	
1PC	TAILGATE 'H' LOGO	na		\$45.00	X
1PC	TAILGATE OUTER HANDLE GARNISH	11		\$450.00	X
2PCS	TAILGATE REFLECTORS @\$386.20	1/5cne 0/5a1		\$772.40	1PC
1PC	TAILGATE INNER LOCK	11		\$199.80	X
1PC	TAILGATE LOCK STRIKER	11		\$66.00	X
1PC	TAILGATE INNER TRIM BOARD	2e/cne	300.80	\$435.00	
1SET	TAILGATE INNER TRIM BOARD CLIPS	nee		\$50.00	
1PC	TAILGATE WEATHERSTRIP	twi		\$288.00	
1PC	REAR BUMPER	122		\$980.00	
2PCS	REAR BUMPER SIDES @\$235.10	1/5 suc 0/5a1	761.00	\$470.20	1PC
2PCS	REAR BUMPER REFLECTORS @\$151.00	1/5cne 0/5a1		\$302.00	1PC
1PC	REAR BUMPER UNDER COVER	2e/twi		\$541.00	
1SET	REAR BUMPER UNDER COVER CLIPS	11	322.80	\$50.00	X
1SET	REAR BUMPER CLIPS	nee		\$50.00	
1PC	REAR END PANEL	12/3ent	517.00	\$665.20	
1PC	REAR END PANEL TOP GARNISH	twi	204.80	\$341.10	
2PCS	TAILLAMPS @\$650.00	1/5cne	480.60	\$1,300.00	1PC
2PCS	TAILLAMP HOUSING PANELS @\$350.00	R		\$700.00	X
1PC	REAR BUZZLE SENSOR	cne		\$98.00	
2PCS	REAR FENDERS @\$1090.00	R		\$2,180.00	X
2PCS	REAR FENDER OUTER PROTECTORS @\$380.00	1/5 Torn 0/5a1 292.50		\$760.00	1PC
2PCS	REAR FENDER INNER TRIM BOARDS @\$395.00	11		\$790.00	X
1PC	REAR FLOOR PANEL	11		\$1,280.00	X
1PC	REAR FLOOR PANEL TOP BOARD	11		\$522.00	X
1PC	REAR FLOOR PANEL TOP TRAY	11		\$585.00	X
1PC	REAR EXHAUST	11		\$765.00	X
1PC	REAR EXHAUST HEAT SHIELD	11	202	\$108.00	X
				\$16,069.90	

#### S.NETT

1PC	REAR WINDSCREEN SEALANT	nee		\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	nee		\$50.00	20
1PC	REAR BUMPER TOP CHROME PLATE	NF		\$200.00	X
1PC	REAR END PANEL TOP GARNISH CROMEE PLATE	NF		\$200.00	X
1PC	REAR END PANEL SEALANT	nee		\$50.00	40
1SET	REAR BUMPER REVERSE SENSOR	malfunction		\$280.00	200
1SET	REAR REVERSE CAMERA	11		\$450.00	X
1SET	REAR FLOOR PANEL INSULATOR	11		\$120.00	X

TO CEHCK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	30
TO DISMANTLE & REFX REAR WINDSCREEN	\$150.00	120
TO TRANSFER TAILGATE MECHANISM	\$100.00	60
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	60
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	11 \$180.00	X
TO DISMANTLE & REFIX REAR EXHAUST	11 \$100.00	X
TO SPRAY RUST PROOFING	\$100.00	50
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00	600
TO PUTTY & SPRAY PAINTING	\$1,500.00	700
<b>TOTAL</b>	<b>\$21,649.90</b>	

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) in a resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p- 5414  
212  
4331.20  
300  
1640  
6271.2  
5014