



QUOTATION

CODE: L0002
CUSTOMER: LONPAC INSURANCE BHD
ADDRESS: 300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

PAGE NO.: 1
DOCUMENT NO.: 2745
DOCUMENT DATE: 23/09/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 15989
REF. NO.: DS/SMD7530R/2049
DATE IN:
EXT. WTY: 30/08/2023
MILEAGE: 0

CONTACT NO.: 6250 7388
MODEL: MAZDA3 1.5L HB DELUXE BLACK LS
CHASSIS NO.: JM6BN24A8J0242364
ENGINE NO.: P520537395
REG NO.: SMD7530R
REGN DATE: 31/08/2018

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	TP CLAIM - LONPAC				0.00	O
SUB	TO REMOVE & REPLACE FRT BUMPER, FRT FENDER RH, FRT DOOR RH, REAR DOOR RH SIDE MIRROR RH.				6,336.00	S
	TO REPAIR REAR FENDER RH & REAR BUMPER. AND ALL ACCIDENT AFFECTED AREA.					
SUB	TO RESPRAY FRT BUMPER, FRT FENDER RH, FRT DOOR RH, REAR DOOR RH, REAR FENDER RH, REAR BUMPER & SIDE MIRROR RH.				6,048.00	S
SUB	TO TRANSFER THE DOOR MECHANISM.				792.00	S
SUB	TO X2 MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.				240.00	S
SUB	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.				560.00	S
SUB	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.				250.00	S
SUB	TO CARRY OUT BODY CAVITY PRESERVATION.				250.00	S
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				250.00	S

**This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.*

**Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.*



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :

5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095
Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042
Service Tel: 6331 0606
Service Fax: 6331 0620



QUOTATION

CODE: L0002
CUSTOMER: LONPAC INSURANCE BHD
ADDRESS: 300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

PAGE NO.: 2
DOCUMENT NO.: 2745
DOCUMENT DATE: 23/09/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 15989
REF. NO.: DS/SMD7530R/2049
DATE IN:
EXT. WTY: 30/08/2023
MILEAGE: 0

CONTACT NO.: 6250 7388
MODEL: MAZDA3 1.5L HB DELUXE BLACK LS
CHASSIS NO.: JM6BN24A8J0242364
ENGINE NO.: P520537395
REG NO.: SMD7530R
REGN DATE: 31/08/2018

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				300.00	S
SUB	SUNDRIES.				50.00	S
B63B-50-031BBE	FRT BUMPER BN WO/FL	1.00	994.32	STOCK	994.32	S
B63B-50-A11 BB	COVER,TOWING HOOK-BU BN	1.00	14.84	STOCK	14.84	S
C274-50-133	NUT,CLIP	12.00	2.36	STOCK	28.32	S
B63B-50-2G2	SEAL,RUBBER BN	2.00	2.36	STOCK	4.72	S
GHP9-50-0Z5	GROMMET,SCREW	2.00	2.36	STOCK	4.72	S
B63C-50-C11A	COVER(R),H BM	1.00	27.40	STOCK	27.40	S
B63C-50-C12	COVER(R),L BN	1.00	85.81	STOCK	85.81	S
B63B-50-102	COVER LHF BUMPER BN	1.00	44.17	STOCK	44.17	S
B63B-50-101	COVER RHF BUMPER BN	1.00	44.17	STOCK	44.17	S
B45A-56-146A	FASTENER	2.00	2.36	STOCK	4.72	S
B63B-50-0T1B	RETAINER RHF FRT BN	1.00	15.77	STOCK	15.77	S
B61K-50-070A	REINF.,FRT BUMPER BN	1.00	576.77	STOCK	576.77	S
BHN1-50-0S0B	STIFF'A',BUMPER BM	1.00	94.57	STOCK	94.57	S
B63C-50-712B	REINF.,RADIATOR GRIL BN	1.00	163.43	STOCK	163.43	S
B63B-50-B41	PROTECTOR,(R) BN	1.00	46.61	STOCK	46.61	S
B63C-50-B41	PROTECTOR,(R)GRILL BN	1.00	47.04	STOCK	47.04	S
B63D-50-B41	PROTECTOR RH GRILL BN	1.00	47.12		47.12	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :

5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095
Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042
Service Tel: 6331 0606
Service Fax: 6331 0620



QUOTATION

CODE: L0002
CUSTOMER: LONPAC INSURANCE BHD
ADDRESS: 300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

PAGE NO.: 3
DOCUMENT NO.: 2745
DOCUMENT DATE: 23/09/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 15989
REF. NO.: DS/SMD7530R/2049
DATE IN:
EXT. WTY: 30/08/2023
MILEAGE: 0

CONTACT NO.: 6250 7388
MODEL: MAZDA3 1.5L HB DELUXE BLACK LS
CHASSIS NO.: JM6BN24A8J0242364
ENGINE NO.: P520537395
REG NO.: SMD7530R
REGN DATE: 31/08/2018

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status		Gross	GST Code
						amount	
			SGD			SGD	
B63C-50-B31	PROTECTOR,GRILLE BN	1.00	85.55	STOCK		85.55	S
B63D-50-B31	PROTECTOR,FRT MOULD BN	1.00	84.04	STOCK		84.04	S
D10J-51-730	MASCOT,FRT BN/DK	1.00	74.18	STOCK		74.18	S
B63B-50-716	BRACKET,RA BN	1.00	26.13	STOCK		26.13	S
B63B-50-7J1A	MOULD RHF RAD GRILL BN	1.00	231.12	STOCK		231.12	S
B63B-50-7K1A	MOULD LHF RAD.GRILLB BN	1.00	231.12	STOCK		231.12	S
B63E-50-B41B	PROTECTOR RHF BUMPER BN	1.00	24.87	STOCK		24.87	S
B63E-50-B51B	PROTECTOR LHF BUMPER BN	1.00	24.87	STOCK		24.87	S
B63C-50-2G2	SEAL,RUBBER BN	2.00	2.36	STOCK		4.72	S
EA01-50-037	RIVET	4.00	7.34	STOCK		29.36	S
B63B-50-153	BRACKET(R),FRT BUMPE BN	1.00	32.79	STOCK		32.79	S
B63B-50-163	BRACKET(L),FRT BUMPER BN	1.00	32.79	STOCK		32.79	S
B63B-50-717	BRACKET RAD GRILL BN	1.00	115.14	STOCK		115.14	S
GD7A-50-EA1	FASTENER	8.00	2.62	STOCK		20.96	S
BHN1-50-1A1C	PLATE NO.1(R),SET-F BN	1.00	37.17	STOCK		37.17	S
TK21-50-355	RIVET	4.00	7.42	STOCK		29.68	S
S51S-51-833	RIVET,SPLASH SHIELD	4.00	3.12	STOCK		12.48	S
B45A-52-111B	RHF FENDER BM/BN	1.00	348.10	STOCK		348.10	S
B4ZA-52-1ROA	STAY RHF FENDER BM/BN	1.00	58.58	STOCK		58.58	S
B45A-56-130H	MUD GUARD RHF BM	1.00	121.80			121.80	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :

5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095
Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042
Service Tel: 6331 0606
Service Fax: 6331 0620



QUOTATION

CODE: L0002
 CUSTOMER: LONPAC INSURANCE BHD
 ADDRESS: 300 BEACH ROAD
 #17-04/07 THE CONCOURSE
 SINGAPORE 199555

PAGE NO.: 4
 DOCUMENT NO.: 2745
 DOCUMENT DATE: 23/09/2024
 POS ID: 12
 PRINTED BY: Lee Yao Sheng
 SERVICE ADV:
 CSP/OP CODE: Lee Yao Sheng
 DEPT: I
 WIP NO.: 15989
 REF. NO.: DS/SMD7530R/2049
 DATE IN:
 EXT. WTY: 30/08/2023
 MILEAGE: 0

CONTACT NO.: 6250 7388
 MODEL: MAZDA3 1.5L HB DELUXE BLACK LS
 CHASSIS NO.: JM6BN24A8J0242364
 ENGINE NO.: P520537395
 REG NO.: SMD7530R
 REGN DATE: 31/08/2018

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
GJ21-68-885B02	FASTENER	6.00	2.36	STOCK	14.16	S
B45A-56-146A	FASTENER	8.00	2.36	STOCK	18.88	S
BHV1-56-114	SHIELD RHF SPLASH BM/BN	1.00	22.85	STOCK	22.85	S
BHY0-58-02XF	DOOR RHF BM/BN	1.00	1,228.97	STOCK	1,228.97	S
BHP2-50-640C	MOULD RHF.BELT.BM/BN	1.00	86.48	STOCK	86.48	S
BHN9-68-911A	WELT,SEAMING BM/BN	1.00	160.99	STOCK	160.99	S
BHN9-58-760C	WEATHERSTRIP RHF DR BM	1.00	110.92	STOCK	110.92	S
KD53-58-210A	HINGE(R),DOOR-UPPER DJ/KE/KG	1.00	45.01	STOCK	45.01	S
D461-59-210B	HINGE'B',DR-LHF LWR DJ/BP/DM	1.00	45.52	STOCK	45.52	S
BC1D-58-762	FASTENER	8.00	2.70	STOCK	21.60	S
GHP9-58-762A	FASTENER	2.00	2.79	STOCK	5.58	S
BHN9-59-760C	WEATHERSTRIP LHF DR BM	1.00	110.92	STOCK	110.92	S
KD47-58-41XG1	LEVER RH OUTER HANDLE BN/GL	1.00	228.76	*NO STOCK	228.76	S
BHN9-58-42XC	BASE RH,HANDLE BM/BN	1.00	70.72	STOCK	70.72	S
KD53-58-414	SEAT(R),HANDLE-OUT BM/GJ/KG	1.00	4.64	STOCK	4.64	S
DF73-58-415G6	CAP,CYL-OUTER HANDLE BM	1.00	29.76	STOCK	29.76	S
GHP9-58-972	COVER,HOLE GL	2.00	4.64	STOCK	9.28	S
BF67-51-261	GROMMET	2.00	1.86	*NO STOCK	3.72	S
BHN9-58-270A	CHECKER,DO BM	2.00	41.73	STOCK	83.46	S
BHS2-69-15YB	GARNISH(R),SAIL-OUT.BM/BN	1.00	26.47		26.47	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :

5 Ubi Close Singapore 408605
 Sales Tel: 6395 8888 Service Tel: 6395 8899
 Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095
 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042
 Service Tel: 6331 0606
 Service Fax: 6331 0620



QUOTATION

CODE: L0002
 CUSTOMER: LONPAC INSURANCE BHD
 ADDRESS: 300 BEACH ROAD
 #17-04/07 THE CONCOURSE
 SINGAPORE 199555

PAGE NO.: 5
 DOCUMENT NO.: 2745
 DOCUMENT DATE: 23/09/2024
 POS ID: 12
 PRINTED BY: Lee Yao Sheng
 SERVICE ADV:
 CSP/OP CODE: Lee Yao Sheng
 DEPT: I
 WIP NO.: 15989
 REF. NO.: DS/SMD7530R/2049
 DATE IN:
 EXT. WTY: 30/08/2023
 MILEAGE: 0

CONTACT NO.: 6250 7388
 MODEL: MAZDA3 1.5L HB DELUXE BLACK LS
 CHASSIS NO.: JM6BN24A8J0242364
 ENGINE NO.: P520537395
 REG NO.: SMD7530R
 REGN DATE: 31/08/2018

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross	GST
					amount	Code
			SGD		SGD	
B63B-69-121A	BODY(R),DOOR MIRROR BN	1.00	457.42	STOCK	457.42	S
B63B-69-1G1	GLASS & HOLDER RH BN/GL	1.00	60.94	STOCK	60.94	S
9YA0-2A-612	BOLT	1.00	2.79	STOCK	2.79	S
BHN9-69-115	COVER(R),HOLE BM/BN/DK	1.00	11.80	STOCK	11.80	S
B63B-69-122A	LAMP(R),SIDE TURN BN/GL	1.00	119.35	STOCK	119.35	S
B63B-69-1N1	13HOUSING RH WM DJ	1.00	127.36	STOCK	127.36	S
BBM6-58-762	FASTENER	2.00	2.70	STOCK	5.40	S
BC1D-58-762	FASTENER	8.00	2.70	STOCK	21.60	S
BJY0-72-02XF	RHR DOOR BM/BN	1.00	1,075.41	STOCK	1,075.41	S
BHP2-50-640C	MOULD RHF.BELT.BM/BN	1.00	86.48	STOCK	86.48	S
BHS2-50-M10A	GARNISH RHF DR BM/BN	1.00	72.41	*NO STOCK	72.41	S
BHS2-50-M30A	GARNISH RHR DR BM/BN	1.00	95.25	STOCK	95.25	S
BHS2-50-M50A	GARNISH RHR DOOR BM/BN	1.00	54.71	*NO STOCK	54.71	S
BAAR-51-031H	HEADLAMP RH BN	1.00	4,335.16	STOCK	4,335.16	S
B63C-51-350A	LAMP(R),F.TURN BN	1.00	168.58	STOCK	168.58	S
B63B-51-680A	FOG LAMP RH BN/KF	1.00	760.77	STOCK	760.77	S
B63B-51-684	BRACKET(R),F.FOG LAM BN	1.00	15.77	STOCK	15.77	S
BHP1-51-153	GASKET(R),RR.COMB.BM/BN	1.00	26.47	STOCK	26.47	S
BHP1-51-163	GASKET(L),RR.COMB BM/BN	1.00	26.47	*NO STOCK	26.47	S
9965-D0-6560	WHEEL,DISC 16X6.5 ALUMI BM/BN/DK	2.00	1,053.58		2,107.16	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :

5 Ubi Close Singapore 408605
 Sales Tel: 6395 8888 Service Tel: 6395 8899
 Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095
 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042
 Service Tel: 6331 0606
 Service Fax: 6331 0620



QUOTATION

CODE: L0002
CUSTOMER: LONPAC INSURANCE BHD
ADDRESS: 300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

PAGE NO.: 6
DOCUMENT NO.: 2745
DOCUMENT DATE: 23/09/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 15989
REF. NO.: DS/SMD7530R/2049
DATE IN:
EXT. WTY: 30/08/2023
MILEAGE: 0

CONTACT NO.: 6250 7388
MODEL: MAZDA3 1.5L HB DELUXE BLACK LS
CHASSIS NO.: JM6BN24A8J0242364
ENGINE NO.: P520537395
REG NO.: SMD7530R
REGN DATE: 31/08/2018

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status		Gross amount	GST Code
				SGD	STOCK	SGD	
GHR1-67-481	TANK,WASHER BN/BM/GL/GJ	1.00	117.50			117.50	S

					Before GST	GST	Total
	* GST Code	Rate	Service/Goods	GST			
Parts	15,947.44	O	-	-			
Surcharge	0.00	S	9.00%	31,023.44	2,792.11	33,815.55	
Labour	15,076.00						
Menus	0.00						
					Gross		
					Less: Deposit**	0.00	0.00
					Amount Due	31,023.44	2,792.11
							33,815.55

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date:

Customer signature

Authorised signature



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042

Service Tel: 6331 0606

Service Fax: 6331 0620