

MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: NO:6 JALAN LAM HUAT, CARROS CENTRE #06-68 S73869

HP: 98888885

Estimation

Date: 22/8/2022
 Vehicle: SNG665D
 Make / Model: TOYOTA ALTIS
 Chassis No: ALLIANC

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	BOOTLID <i>repair</i> XR	1	\$ 858.00	\$ 858.00
2	BOOTLID EMBLEM 'COROLLA' <i>new</i>	1	\$ 52.00	\$ 52.00
3	BOOTLID EMBLEM ;ALTIS' <i>new</i>	1	\$ 48.00	\$ 48.00
4	BOOTLID LOGO <i>new</i>	1	\$ 58.00	\$ 58.00
5	REAR BUMPER ? XR	1	\$ 698.00	\$ 698.00
6	REAR BUMPER SIDE RETAINER RH X NN	1	\$ 112.00	\$ 112.00
7	REAR BUMPER BRACKET RH X NN	1	\$ 168.00	\$ 168.00
8	REAR BUMPER REINFORCEMENT X NN	1	\$ 395.00	\$ 395.00
9	REAR BUMPER REFLECTOR RH X NN	1	\$ 112.00	\$ 112.00
				\$ 1,485.00
			Less 25%	\$ 371.25
			Total	\$ 1,113.75

	S/Nett items:				
1	REAR REVERSE SENSOR <i>new</i>	1	\$ 250.00	\$ 250.00	<i>200</i>
2	REAR BUMPER CLIP SET <i>new</i>	1	\$ 80.00	\$ 80.00	<i>36</i>
				\$ 330.00	
	Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00	<i>400 X</i>
2	TO REMOVE AND REFIT REVERSE SENSOR / CAMERA		\$ 150.00	\$ 150.00	<i>400 ? ✓</i>
3	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00	<i>X</i>
4	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00	<i>200</i>
5	PANEL BEATING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00	<i>200</i>
				\$ 1,630.00	
<i>Repair</i> <i>HP 98888885</i> <i>3 days</i> <i>4/5</i> <i>08/09/22 @ 1640</i> <i>Res after repair</i>			Parts Replacement Amount	\$ 1,443.75	
			Total Amount for Labour	\$ 1,630.00	
			Total Amount	\$ 3,073.75	