



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref:	CS/FCI24090402/Kqp3e2
		Date:	10/10/2024
		Code:	FCI2
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 3510A	Veh. Inspected	SHC 5635A
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24007964MFCT	Excess	\$0.00
Assign From	AINI	Assign Date	23/09/2024
2. Vehicle Details			
Make & Model	TOYOTA PRIUS (A)	C.C	1798
Engine No.	2ZR2N56789	Year of Reg.	30/09/2022
Chassis No.	JTDKB3FUX03096054	Colour	METALLIC PEARL WHITE / RED
Odometer	268828 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		
3. Conditions of Tyres			
	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	WANLI	9
L/H Front Tyre	195/65R15	WANLI	9
R/H Rear Tyre	195/65R15	WANLI	7
L/H Rear Tyre	195/65R15	WANLI	7
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/09/2024	Inspection Date	24/09/2024
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD - NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			