

Not Authorized
 Recovery B4 paint

11 Imp & Book

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No Fax No. : 62571330
 CO./ GST Reg. No. 201019626G
SHC5635A

AAD2409-046

Vehicle No.:
 Chassis No.:
 Co UEN.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident:
 Third Party Insurer:
 Date of Registration:

24 SEP 2024

SHC5635A
 JTKB3FUX03096054
 200303878K
 TOYOTA
 PRIUS GEN 4
 9/9/2024
 SHA3510A/MSFCI
 30/9/2022

PART

LIST

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 LENS & BODY, REAR COMBINATION LAMP, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH
- 1 COVER, REAR COMBINATION LAMP, RH

| | | | |
|----|---------|----------|---|
| \$ | Red Mfg | 612.68 | ✓ |
| \$ | Sm | 27.93 | X |
| \$ | Sm | 472.19 | X |
| \$ | Sm | 49.25 | } |
| \$ | Sm | 149.21 | |
| \$ | Sm | 167.48 | |
| \$ | R | 419.90 | |
| \$ | Sm | 220.50 | |
| \$ | Sm | 304.92 | |
| \$ | Sm | 290.43 | |
| \$ | Sm | 159.39 | |
| \$ | R | 824.46 | |
| \$ | Sm | 1,156.89 | |
| \$ | Sm | 428.19 | |
| \$ | Sm | 329.49 | |
| \$ | Sm | 88.41 | |

TOTAL \$ **5,701.32**
 25% \$ **1,425.33**
 \$ **4,275.99**

SPECIAL NETT

- 1SET PARKING AID
- 1 REAR BUMPER CLIP
- 1 REAR LH BUMPER RETAINER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING

| | | | |
|----|----|--------|------|
| \$ | Sm | 700.00 | X |
| \$ | na | 65.00 | 6000 |
| \$ | na | 65.00 | X |
| \$ | na | 65.00 | X |
| \$ | na | 60.00 | X |
| \$ | na | 180.00 | 3000 |
| \$ | na | 150.00 | X |
| \$ | na | 200.00 | X |

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel Nc Fax No. : 62571330
 CO./ GST Reg. No. 201019626G
SHC5635A

AAD2409-046

1 WINDSCREEN INNER SPONGE SEAL

| | | | | |
|--------------------|----|-----------|-----------------|---|
| | \$ | <i>na</i> | 130.00 | X |
| TOTAL | \$ | | 1,615.00 | |
| TOTAL PARTS | \$ | | 5,890.99 | |

LABOUR

| | | | | |
|---|----|-----------|------------------|-------------|
| To rust-proofing of the affected areas. | \$ | <i>na</i> | 600.00 | X |
| Putty and spray painting of the affected portion. | \$ | | 1,200.00 | <i>2201</i> |
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | | 2,000.00 | <i>1801</i> |
| To transfer of tailgate fittings and conduct water seepage test. | \$ | <i>na</i> | 170.00 | X |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$ | <i>L</i> | 380.00 | X |
| To transfer of tailgate fittings and conduct water seepage test. | \$ | <i>L</i> | 170.00 | X |
| To reinstall rear bumper parking sensor. | \$ | | 170.00 | <i>501</i> |
| To check steering geometry and computer wheel alignment | \$ | <i>L</i> | 220.00 | X |
| To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test. | \$ | <i>L</i> | 170.00 | X |
| TOTAL | \$ | | 5,080.00 | |
| OVERALL TOTAL | \$ | | 10,970.99 | |

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: