

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	ALLIED WORLD AS	SURANCE COMPANY LTD	Ref:	CS/AWA24090403/Uvp3	
	(SINGAPORE BRANCH)		Date:	10/10/2024	
	60 ANSON ROAD #08-01 (8TH FLOOR) MAPLETREE ANSON SINGAPORE 079914		Code:	AWA	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 3243K	Veh. Inspected	SGT 9188U	
	Policy No.	BVF2SB0002812301	Coverage	0	
	Claim No.	XE 3243K/PC	Excess	\$0.00	
	Assign From	HEW LEE FONG	Assign Date	23/09/2024	
2. Vehicle Details					
	Make & Model	AUDI A5 SB (A)	C.C	1984	
	Engine No.	CVK084178	Year of Reg.	29/07/2019	
	Chassis No.	WAUZZZF54KA059955	Colour	GREY	
	Odometer	125159 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	265/30ZR20	PIRELLI	6	
	L/H Front Tyre	265/30ZR20	PIRELLI	6	
	R/H Rear Tyre	265/30ZR20	PIRELLI	6	
	L/H Rear Tyre	265/30ZR20	PIRELLI	6	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	23/09/2024	Inspection Date	24/09/2024	
	Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD - 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a.	5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days