

SAFE AUTO

Reg No:
Blk 25 kaki bukit road 4 #05-83 S(417800)
Mobile no: 97777040
Email : safeauto88@hotmail.com

Xiao Chen.

24 September 2024

QUOTATION FOR ACCIDENT REPAIR OF SMC9427Z HYUNDAI ACCENT

THIRD PARTY INSURER: LIBERTY

S/No.	Parts List	Qty	Amount (\$)
1.	Rear boot lid <i>Repair</i>	1	\$ 907.00 +
2.	Rear boot lid Logo emblem <i>Green</i>	1	\$ 65.00 ✓
3.	Rear boot lid Accent emblem	1	\$ 68.00 ✓
4.	Rear boot lid weather strip <i>Green</i>	1	\$ 155.00 +
5.	Rear boot lid mechanism lock	1	\$ 175.00 +
6.	Rear taillamp L/R <i>ut</i>	2	\$ 1060.00 830
7.	Rear bumper <i>Deformed</i>	1	\$ 553.00 ✓
8.	Rear bumper side reflector lamp <i>new</i>	2	\$ 156.00 +
9.	Rear bumper reinforcement <i>cracked</i>	1	\$ 428.00 ✓
10.	Rear bumper reinforcement bracket <i>Deformed</i>	4	\$ 220.00 80.
11.	Rear end panel <i>Dented</i>	1	\$ 455.00 ✓
12.	Rear end panel garnish <i>Deformed</i>	1	\$ 162.00 ✓

Subtotal before discount \$ 4404.00

Discount 20% \$ 880.80

Subtotal 1 \$ 3523.20

S/Nett. Parts List Qty Amount (\$)

1.	Rear bumper clip <i>New</i>	1	\$ 30.00 ✓
2.	Rear bumper reverse sensor (4pcs) <i>New</i>	1	\$ 450.00 X
3.	rear end panel garnish clip <i>New</i>	1	\$ 30.00 20.

S/Nett Total \$ 510.00

Rear Labour

To check wiring and rectify electrical faults where necessary	\$ 60 30
To remove and refit rear fender inner trims and attachment to facilitate the repairs.	\$ 150 60
To remove and replace reverse sensors and check/program sensing distance	\$ 120 50
To straighten, repair, realign on front affected area and replace damaged parts	\$ 1000 700
To spray painting on affected area	\$ 1000 700

Total Labour Cost \$ 2330

total: 3702.80
1/8: 2950.
05 Days.

Liberty Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: