

FIRST GARAGE PTE LTD

13 Kaki Bukit Rd 4, #03-30 Bartley Biz Centre, Singapore 417807
GORDON HP: 98528570

ESTIMATED REPAIR COSTS FOR SNN4408S

MODEL : TOYOTA NOAH

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>
1PC	REAR RIM RH X nn	\$ 1,549.20
1PC	REAR WHEEL BEARING & HUB ASSY RH X nn	\$ 761.20
1PC	REAR WHEEL AXLE X nn	\$ 2,547.00
1PC	REAR ABSORBER RH X nn	\$ 787.00
1PC	REAR FENDER RH X R	\$ 3,110.90
1PC	REAR FENDER QUARTER GLASS MOULDING WITH GLASS RH X nn	\$ 1,233.40
1PC	REAR FENDER INNER SHIELD RH X nn	\$ 251.90
1PC	REAR FENDER AIR DUCT RH X nn	\$ 114.20
1PC	REAR BUMPER / RY	\$ 1,880.20
1PC	REAR BUMPER REFLECTOR RH ? BR	\$ 289.00
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$85.90 EACH ? BR	\$ 171.80
1PC	TAIL LAMP LOWER GARNISH RH ? BR	\$ 349.20

PARTS SUM: \$ 13,045.00
PARTS LESS 25%: \$ 3,261.25
PARTS TOTAL: \$ 9,783.75

1445 /
131 /
85.90 /
244 /

1905.90
-25%
1429.42

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY 1PC TYRE	MISC ITEMS	\$ 300.00 X nn
*	TO SUPPLY 1PC RIM	"	\$ 1,200.00 X nn
*	TO SUPPLY SIDE SKIRT CLIPS	"	\$ 50.00 X nn
*	TO SUPPLY ROCKER PANEL SEALANT	"	\$ 80.00 X nn
*	TO SUPPLY REAR FENDER SEALANT	"	\$ 80.00 X nn
*	TO SUPPLY REAR FENDER QUARTER GLASS SEALANT	"	\$ 80.00 X nn
*	TO SUPPLY REAR FENDER QUARTER GLASS DAMPING SEAL	"	\$ 30.00 X nn
*	TO SUPPLY BUMPER CLIPS	"	\$ 50.00 ? Nec
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS		\$ 300.00 X
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS		\$ 2,400.00 300

*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,400.00	500
*	TO APPLY ANTI-RUST COATINGS ON ALL AFFECTED AREAS	\$ 300.00	X
*	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 250.00	X
*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	\$ 120.00	X
*	TO RNR REAR SLIDING DOOR TO FACILITATE REPAIRS	\$ 250.00	X
*	TO RNR REAR SLIDING DOOR MECHANISM TO FACILITATE REPAIRS	\$ 150.00	X
*	TO RE-ALIGN REAR SLIDING DOOR RAILING ALIGNMENT	\$ 150.00	X
*	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	\$ 300.00	X
*	TO RNR REAR FENDER FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	\$ 300.00	X
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	50
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00	50
*	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	\$ 120.00	50

LABOUR & S/N TOTAL: \$ 9,410.00

980

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 19,193.75

Steve (LKK)
24/6/24, 2.30pm

W R

L/S

L/L Y
3 d/s

2409.42

L/S - 1927.53
= 1950

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: