

FIRST GARAGE PTE LTD

13 Kaki Bukit Rd 4, #03-30 Bartley Biz Centre, Singapore 417807
GORDON HP: 98528570

ESTIMATED REPAIR COSTS FOR SNN4408S

MODEL : TOYOTA NOAH

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>
1PC	REAR RIM RH X	\$ 1,549.20
1PC	REAR WHEEL BEARING & HUB ASSY RH X	\$ 761.20
1PC	REAR WHEEL AXLE X	\$ 2,547.00
1PC	REAR ABSORBER RH X	\$ 787.00
1PC	REAR FENDER RH X R	\$ 3,110.90
1PC	REAR FENDER QUARTER GLASS MOULDING WITH GLASS RH X	\$ 1,233.40
1PC	REAR FENDER INNER SHIELD RH X	\$ 251.90
1PC	REAR FENDER AIR DUCT RH X	\$ 114.20
1PC	REAR BUMPER / RY	\$ 1,880.20
1PC	REAR BUMPER REFLECTOR RH ?	\$ 289.00
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$85.90 EACH ?	\$ 171.80
1PC	TAIL LAMP LOWER GARNISH RH ?	\$ 349.20

PARTS SUM: \$ 13,045.00

PARTS LESS 25%: \$ 3,261.25

PARTS TOTAL: \$ 9,783.75

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY 1PC TYRE	\$ 300.00 X
*	TO SUPPLY 1PC RIM	\$ 1,200.00 X
*	TO SUPPLY SIDE SKIRT CLIPS	\$ 50.00 X
*	TO SUPPLY ROCKER PANEL SEALANT	\$ 80.00 X
*	TO SUPPLY REAR FENDER SEALANT	\$ 80.00 X
*	TO SUPPLY REAR FENDER QUARTER GLASS SEALANT	\$ 80.00 X
*	TO SUPPLY REAR FENDER QUARTER GLASS DAMPING SEAL	\$ 30.00 X
*	TO SUPPLY BUMPER CLIPS	\$ 50.00 30
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	\$ 300.00 X
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,400.00 150

*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,400.00	500
*	TO APPLY ANTI-RUST COATINGS ON ALL AFFECTED AREAS	\$ 300.00	X
*	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 250.00	X
*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	\$ 120.00	X
*	TO RNR REAR SLIDING DOOR TO FACILITATE REPAIRS	\$ 250.00	X
*	TO RNR REAR SLIDING DOOR MECHANISM TO FACILITATE REPAIRS	\$ 150.00	X
*	TO RE-ALIGN REAR SLIDING DOOR RAILING ALIGNMENT	\$ 150.00	X
*	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	\$ 300.00	X
*	TO RNR REAR FENDER FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	\$ 300.00	X
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	30
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00	X
*	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	\$ 120.00	30

LABOUR & S/N TOTAL: \$ 9,410.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 19,193.75

Steve (LKK)

24/6/24, 2.30pm

W R

L/S

L L L L

3 d/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: