



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2503433
3 ANSON ROAD #16-00	INV Date	02/06/2025
SPRINGLEAF TOWER	Reference	CD/CTI24090408/Apa3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	SMP 7730S
Insured Veh.	GBG 6982R
Claim No.	SNM24D205357
Policy No.	DMCVSNA00099422302
Accident Date	03/08/2024
Inspection Date	23/09/2024

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (9%)</b>	<b>36.00</b>
<b>Grand Total</b>	<b>436.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CD/CTI24090408/Apa3q2(N) Date: 02/06/2025 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBG 6982R	Veh. Inspected	SMP 7730S
Policy No.	DMCVSNA00099422302	Coverage (\$)	0.00
Claim No.	SNM24D205357	Excess (\$)	0.00
Assign From		Assign Date	23/09/2024
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI AVANTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHD841CMLU997563	Colour	WHITE
Odometer	321258 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	HANKOOK	6 mm
L/H Front Tyre	205/55 R16	HANKOOK	6 mm
R/H Rear Tyre	205/55 R16	HANKOOK	6 mm
L/H Rear Tyre	205/55 R16	HANKOOK	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/08/2024	Inspection Date	23/09/2024
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 7730S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER	DEFORMED	474.40	474.40
1	FRONT BUMPER LOWER LIP	NOT NECESSARY	71.70	-
1	FRONT BUMPER FOGLAMP C/W BRACKET RH	NOT NECESSARY	165.00	-
1	FRONT BUMPER FOG LAMP LOWER GARNISH RH	NECESSARY	115.40	115.40
2	FRONT BUMPER SIDE RETAINER @\$16.00	NOT NECESSARY	32.00	-
1	FRONT BUMPER AIR VENT LH	DEFORMED	24.40	24.40
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	695.80	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	110.70	-
1	FRONT BUMPER LOWER BEAM	NOT NECESSARY	119.00	-
1	FRONT BUMPER BOTTOM GARNISH	NOT NECESSARY	133.30	-
2	FRONT BUMPER CENTER BRACKET @\$49.20	NOT NECESSARY	98.40	-
1	FRONT SIDE MIRROR RH	NOT NECESSARY	1,332.90	-
2	HEAD LAMP @\$3034.90	N/S CRACKED	6,069.80	3,034.90
1	HEAD LAMP LOWER BRACKET LH	NOT NECESSARY	24.00	-
2	HEAD LAMP CLIP @\$28.60	NOT NECESSARY	57.20	-
1	CENTER GRILLE	NOT NECESSARY	1,214.30	-
1	CENTER GRILLE LOGO	NOT NECESSARY	128.30	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	949.30	-
1	WASHER TANK	NOT NECESSARY	238.00	-
1	FRONT FENDER LH	DENTED	1,227.70	1,227.70
2	FRONT FENDER INNER COWLING LH @\$85.70	NOT NECESSARY	171.40	-
1	FRONT ABS SENSOR LH	NOT NECESSARY	201.90	-
1	FRONT KNUCKLE ARM LH	NOT NECESSARY	309.70	-
1	FRONT LOWER ARM LH	NOT NECESSARY	282.80	-
1	FRONT WHEEL HUP LH	NOT NECESSARY	168.30	-
1	FRONT KNUCKLE ARM BEARING LH	NOT NECESSARY	124.60	-
1	FRONT STABILIZER BAR LINKAGE LH	NOT NECESSARY	79.40	-
1	FRONT DRIVESHAFT LH	NOT NECESSARY	986.70	-
1	FRONT SHOCK ABSORBER LH	NOT NECESSARY	234.60	-
1	FRONT STEERING RACK AND PINION	NOT NECESSARY	1,168.50	-

Report Ref No. CD/CTI24090408/Apa3q2(N)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-3,401.90	-975.36
			13,607.60	3,901.44
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	SET FRONT BUMPER FOG LAMP LOWER GARNISH CLIP (SN)	NOT NECESSARY	60.00	-
1	SET FRONT ENGINE UNDER COVER CLIP (SN)	NOT NECESSARY	80.00	-
1	SET FRONT FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	80.00	-
1	SET CENTER GRILLE CLIP (SN)	NOT NECESSARY	60.00	-
1	SET CENTER GRILLE TOP COVER GARNISH CLIP (SN)	NOT NECESSARY	60.00	-
1	FRONT TYRE RH (SN)	NOT NECESSARY	380.00	-
1	FRONT WHEEL SPORT RIM RH (SN)	NOT NECESSARY	450.00	-
1	SET FRONT WHEEL HUP (SN)	NOT NECESSARY	80.00	-
1	BRAKE OIL (SN)	NOT NECESSARY	80.00	-
			1,460.00	30.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING ,REMOVING AND REPLACING PARTS.		1,600.00	400.00
	SPRAY PAINTING TO AFFECTED AREA.		1,400.00	400.00
	REFOCUS HEADLAMP BEAM.	NOT NECESSARY	60.00	-
	REMOVE AND REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	850.00	-
	FOUR WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX POWER STEERING RACK AND PINION.	NOT NECESSARY	350.00	-
	RESET ABS LIGHT .	NOT NECESSARY	350.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			4,910.00	800.00
	<b>GRAND TOTAL</b>		<b>19,977.60</b>	<b>4,731.44</b>

Report Ref No. CD/CTI24090408/Apa3q2(N)



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,700.00</b>
---	--	--	-----------------

Report Ref No. CD/CTI24090408/Apa3q2(N)

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. : SMP 7730S



**PHOTOGRAPHS FOR VEHICLE NO. : SMP 7730S**



**PHOTOGRAPHS FOR VEHICLE NO. : SMP 7730S**



**PHOTOGRAPHS FOR VEHICLE NO. : SMP 7730S**





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 5 of 5)

## PHOTOGRAPHS FOR VEHICLE NO. : SMP 7730S



**PHOTOGRAPHS FOR VEHICLE NO. : SMP 7730S**



**PHOTOGRAPHS FOR VEHICLE NO. : SMP 7730S**



**PHOTOGRAPHS FOR VEHICLE NO. : SMP 7730S**





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

REINSPECTION PHOTOS (Page 4 of 5)

## PHOTOGRAPHS FOR VEHICLE NO. : SMP 7730S



**PHOTOGRAPHS FOR VEHICLE NO. : SMP 7730S**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

### PHOTOGRAPHS FOR VEHICLE NO. : SMP 7730S





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

### PHOTOGRAPHS FOR VEHICLE NO. : SMP 7730S

