

**AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.**

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)
Tel : 6702 1555 Fax : 6702 1444
Co. Reg No. : 201500047H GST No. : 201500047H
Email : st.sim@autobacs.com.sg

TO	: INCOME INSURANCE (GBD3381K)	DATE	: 23-Sep-24
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX704Z	P -	
		S -	
		L -	
		TOTAL	:
		L/S -20%	:
		SUB TOTAL	:
VEHICLE DETAILS			
VEHICLE NO.	: SLP7791C		
MODEL / MAKE	: HYUNDAI ELANTRA		
CHASSIS NO.	: KMHD841CMHU462203		
ACCIDENT DETAIL			
DATE	: 19-Sep-24		
TIME	: 14:30 HRS		
		CONTACT PERSON	: MR. SIM 9844 0974

QUOTATION SUMMARY PAGE 01**CLAIMS DETAIL : PARTS LIST**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER	1	\$ 850.00	\$ 850.00
2	R/R TAILLAMP	1	\$ 350.00	\$ 350.00
3	REAR BOOT	1	\$ 1,500.00	\$ 1,500.00
4	REAR END PANEL 512	1	\$ 245.00	\$ 245.00
5	REAR BUMPER LOWER DIFFUSER	1	\$ 400.00	\$ 400.00
6	REAR BUMPER LH REFLECTOR	1	\$ 68.00	\$ 68.00
TOTAL PRICE				\$ 3,413.00
SUB TOTAL PRICE				\$ 3,413.00

QUOTATION SUMMARY PAGE 02**CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING**

TO REMOVE REAR BUMPER, AND BUMPER REINFORCEMENT OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS	\$ 500.00	400	
TO RESPRAY REAR BOOT AND REAR BUMPER	\$ 500.00	✓	

TOTAL \$ 1,000.00

ESTIMATE REPORT

TOTAL PARTS COST	:	\$ 3,413.00
TOTAL LABOUR COST	:	\$ 1,000.00
TOTAL REPAIR COST	:	\$ 4,413.00

APPROVED DETAILS

NO. OF REPAIR DAYS :
REPAIR UNDER :
DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
EMAIL ADDRESS :
DATE / TIME OF RE-SURVEY :

PART BY PART OR LUMP SUM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 972
222
P- 777-60
L- 900
1677-60
222
1342.