

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 23.09.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SJK9256T**
MODEL : **TOYOTA NOAH**
DATE OF ACCIDENT : 20.09.2024
TIME OF ACCIDENT : 07:10 HOURS

Xiao Chan.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rehnd</i>	1	\$ 1,265.70	\$ 1,265.70
2	FRONT BUMPER FOG LAMP COVER RH <i>Xhe m</i>	1	\$ 79.20	\$ 79.20
3	FRONT BUMPER LOWER GRILLE <i>Xhe m</i>	1	\$ 184.20	\$ 184.20
4	FRONT BUMPER SIDE RETAINER <i>he m</i>	2	\$ 85.60	\$ 171.20
5	HEADLAMP RH <i>Cuehd</i>	1	\$ 1,925.30	\$ 1,925.30
6	FRONT UPPER GRILLE <i>Xhe m</i>	1	\$ 804.60	\$ 804.60
7	FRONT FENDER RH <i>Regis</i>	1	\$ 974.30	\$ 974.30
8	FRONT FENDER INNER COWLING RH <i>Xhe m</i>	1	\$ 219.60	\$ 219.60
9	FRONT WHEEL RIM RH <i>lit</i>	1	\$ 1,219.30	\$ 1,219.30
10	FRONT ABS SENSOR RH <i>he m</i>	1	\$ 397.20	\$ 397.20
11	FRONT STEERING RACK AND PINION <i>Best</i>	1	\$ 1,667.30	\$ 1,667.30
12	FRONT DRIVESHAFT RH <i>Xhe m</i>	1	\$ 1,448.60	\$ 1,448.60
13	FRONT KNUCKLE ARM BEARING RH <i>Rehd</i>	1	\$ 201.70	\$ 201.70
14	FRONT STABILIZER BAR LINKAGE RH <i>3he</i>	1	\$ 173.70	\$ 173.70
15	FRONT SHOCK ABSORBER RH <i>hm</i>	1	\$ 441.30	\$ 441.30
16	FRONT KNUCKLE ARM RH <i>Rehd</i>	1	\$ 565.70	\$ 565.70
17	FRONT LOWER ARM RH <i>Best</i>	1	\$ 997.60	\$ 997.60

5930
4447.50

S.N: 480

TOTAL PRICE \$ 12,736.50
LESS 25% \$ 3,184.13
SUB TOTAL PRICE \$ 9,552.38

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	-------------	--------------

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJK9256T**
 MODEL : **TOYOTA NOAH**
 DATE OF ACCIDENT : 20.09.2024
 TIME OF ACCIDENT : 07:10 HOURS

1	FRONT BUMPER CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
2	FRONT BUMPER LOWER GRILLE CLIP (SET) <i>neu</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
3	FRONT BUMPER UNDER COVER GARNISH CLIP (SET) <i>neu</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
4	FRONT UPPER GRILLE CLIP (SET) <i>neu</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
5	FRONT FENDER COWLING CLIPS (SET) <i>neu</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
6	FRONT WHEEL TYRE RH <i>neu</i>	1	\$ 650.00	\$ 650.00	<i>+</i>
7	BRAKE OIL <i>neu</i>	1	\$ 30.00	\$ 30.00	<i>+</i>

30

TOTAL \$ 980.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	<i>300</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>400</i>
3	TUFF COAT	\$ 250.00	<i>30</i>
4	WIRING CHECK	\$ 80.00	<i>30</i>
5	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>+</i>
6	REMOVE AND REFIX STEERING RACK PINION	\$ 350.00	<i>+</i> <i>120</i>
7	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	<i>200</i>
8	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>80</i>
9	FRONT CHASSIS ALIGNMENT	\$ 250.00	<i>+</i>
10	RESET ABS LIGHT	\$ 350.00	<i>+</i>

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SJK9256T**
MODEL : **TOYOTA NOAH**
DATE OF ACCIDENT : 20.09.2024
TIME OF ACCIDENT : 07:10 HOURS

11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

1160

TOTAL \$ 4,490.00

TOTAL PARTS COST : \$ 10,532.38
TOTAL LABOUR COST : \$ 4,490.00
TOTAL REPAIR COST : \$ 15,022.38

Adrian Li
R/S 24/09/24
05 hrs.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Total: 6117.50

L/S: 4.9K. ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: