

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24090413/ANP3M4**Date:** 04/12/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003503568
Claimant Vehicle No :	SKG8111T	Insured Vehicle No :	SLT9382R
Date of Loss:	19/09/2024	Nature of Claim:	TP
		Claim No:	373903

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG8111T		
Make & Model:	AUDI A5, 2.0 DESIGN TFSI S TRONIC (A)	Engine No:	CVK065828
Reg. Date:	31/08/2019 (Man. Year: 2018)	Chassis No:	WAUZZZF5XJA121812
Colour:	Red	Odometer:	0 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,646.00	14,758.60	2,887.40	16.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,330.00	4,880.00	2,450.00	33.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,976.00	19,638.60	5,337.40	21.37
+ GST 9.00/9.00% (S\$)	2,247.84	1,767.47	480.37	21.37
Nett Amount (S\$)	27,223.84	21,406.07	5,817.77	21.37

INSPECTION

Date of Assignment:	24/09/2024	
Date Inspected:	25/09/2024	Inspected At: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2024)
Parts:	143	AUDI A5 2.0 DESIGN TFSI S TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKG8111T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,802.00 FS	*2,802.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	458.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	45.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	286.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	71.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	598.00 FS	*597.50 FS
7	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	46.00 FS	*- FS
8	1		*FRONT PARKING AID SENSOR	Not Necessary	286.00 FS	*- FS
9	1		*LED HEADLIGHT - RH	Cut	9,447.00 FS	*9,447.00 FS
10	3		*LED HEADLIGHT SPACER - RH	Not Necessary	150.00 FS	*- FS
11	1		*LIFT CYLINDER - RH	Not Necessary	19.00 FS	*- FS
12	1		*LIFT CYLINDER HOSE - RH	Not Necessary	110.00 FS	*- FS
13	1		*HEADLIGHT TOP COVER - RH	Not Necessary	20.00 FS	*- FS
14	1		*FRONT FENDER - RH	Dented	1,264.00 FS	*1,264.00 FS
15	1		*FRONT FENDER ATTACHMENT PARTS - RH	Not Necessary	62.00 FS	*- FS
16	1		*FRONT FENDER CLOSING ELEMENT - RH	Damaged	92.00 FS	*92.00 FS
17	1		*FRONT FENDER BRACKET - RH	Not Necessary	45.00 FS	*- FS
18	6		*FRONT FENDER RIVET - RH	Not Necessary	26.00 FS	*- FS
19	1		*FRONT FENDER BRACKET - RH	Not Necessary	73.00 FS	*- FS
20	1		*FRONT FENDER BRACKET - RH	Not Necessary	56.00 FS	*- FS
21	1		*FRONT FENDER BRACE - RH	Bent	177.00 FS	*176.50 FS
22	1		*FRONT FENDER LOWER BRACKET - RH	Not Necessary	72.00 FS	*- FS
23	1		*FRONT FENDER COVER - RH	Necessary	45.00 FS	*44.20 FS
24	1		*FRONT FENDER COVER - RH	Not Necessary	90.00 FS	*- FS
25	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	332.00 FS	*- FS
26	1		*FRONT WHEEL SPOILER - RH	Torn	92.00 FS	*91.40 FS
27	1		*WHEEL HOUSING LINER ATTACHMENT PARTS - RH	Not Necessary	190.00 FS	*- FS
28	1		*FRONT FENDER CHROME TRIM - RH	Necessary	192.00 FS	*192.00 FS
29	1		*SUNDRIES	Necessary	500.00 FS	*52.00 FS
Total Parts (S\$)						17,646.00 14,758.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT	New	3,850.00	2,200.00
2	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	3,000.00	2,200.00
3	TO CARRY OUT DIAGNOSTIC CHECK	New	480.00	480.00
Gross Labour Cost (S\$)			7,330.00	4,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >