

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0704/2024/EQ
DATE : 23-Sep-24
WIP : 31752

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/9/2024

YOUR INSURED VEH NO :SLT 9382 R

MSIG Insurance (Singapore) Pte Ltd

4 Shenton Way

#21-01 SGX Centre 2

Singapore 068807

Attn: Motor Claims Dept

OWNER'S NAME : MS CAROLYN WOO WAI-LING
ADDRESS : 315 BUKIT TIMAH ROAD
#03-02
SINGAPORE 259710
TELEPHONE : HP +65 96680125
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900149559-02
VEHICLE NO : **SKG 8111 T**
MODEL CODE : AUDI A5 COUPE TFSI
MODEL YEAR : 31/8/2019
ENGINE NO : CVK 065828
CHASSIS NO : WAUZZZF5XJA121812
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Sep-24
PLACE OF ACCIDENT : BLK110A TOA PAYOH HDB (MSCP)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKG 8111 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT.	\$ 3,850.00	 2200
2	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 3,000.00	 2200
3	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 480.00	
TOTAL LABOUR CHARGES		: \$ 7,330.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 8111 T.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Replaced</i>	1	\$ 2,802.00	✓
2	FRONT BUMPER FIXING PARTS	1	\$ 458.00	+
3	FRONT BUMPER SECURING STRIP <i>Green</i>	1	\$ 45.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Replaced</i>	1	\$ 286.00	+
5	FRONT BUMPER AIR GUIDE - RH <i>Replaced</i>	1	\$ 71.00	+
6	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Replaced</i>	1	\$ 598.00	+
7	FRONT BUMPER GUIDE SECTION - RH <i>Replaced</i>	1	\$ 46.00	+
8	FRONT PARKING AID SENSOR <i>Replaced</i>	1	\$ 286.00	+
9	LED HEADLIGHT - RH <i>Replaced</i>	1	\$ 9,447.00	✓
10	LED HEADLIGHT SPACER - RH <i>Not Replaced</i>	3	\$ 150.00	x
11	LIFT CYLINDER - RH <i>Replaced</i>	1	\$ 19.00	+
12	LIFT CYLINDER HOSE - RH <i>Replaced</i>	1	\$ 110.00	+
13	HEADLIGHT TOP COVER - RH <i>Replaced</i>	1	\$ 20.00	+
14	FRONT FENDER - RH <i>Dented.</i>	1	\$ 1,264.00	✓
15	FRONT FENDER ATTACHMENT PARTS - RH <i>Replaced</i>	1	\$ 62.00	+
16	FRONT FENDER CLOSING ELEMENT - RH <i>Replaced</i>	1	\$ 92.00	+
17	FRONT FENDER BRACKET - RH <i>Not Replaced</i>	1	\$ 45.00	+
18	FRONT FENDER RIVET - RH <i>Not Replaced</i>	6	\$ 26.00	+
19	FRONT FENDER BRACKET - RH <i>Replaced</i>	1	\$ 73.00	+
20	FRONT FENDER BRACKET - RH <i>Replaced</i>	1	\$ 56.00	+
SUB TOTAL SPARE PARTS			\$ 15,956.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 8111 T.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACE - RH	1	\$ 177.00	+
22	FRONT FENDER LOWER BRACKET - RH	1	\$ 72.00	+
23	FRONT FENDER COVER - RH	1	\$ 45.00	?
24	FRONT FENDER COVER - RH	1	\$ 90.00	?
25	FRONT WHEEL HOUSING LINER - RH	1	\$ 332.00	+
26	FRONT WHEEL SPOILER - RH	1	\$ 92.00	+
27	WHEEL HOUSING LINER ATTACHMENT PARTS - RH	1	\$ 190.00	+
28	FRONT FENDER CHROME TRIM - RH	1	\$ 192.00	✓
29	SUNDRIES		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 17,646.00	
TOTAL LABOUR CHARGES		:	\$ 7,330.00	
GRAND TOTAL		:	\$ 24,976.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian King
25/09/24

Not Authorised, 04 Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT