



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CS3/LPC24090415/Evh3e2
300 BEACH ROAD	Date:	02/10/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- PRE-REPAIR SURVEY

Insured Veh.	XE 8558U	Veh. Inspected	SMW 5889U
Policy No.	-	Coverage	0
Claim No.	23/24/24/VC05/029899	Excess	\$0.00
Assign From	ERIC	Assign Date	24/09/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ C160	C.C	1497
Engine No.	26491580048396	Year of Reg.	30/09/2020
Chassis No.	W1K2050752R592575	Colour	GREY
Odometer	70385 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45 R17	MICHELIN	5
L/H Front Tyre	225/45 R17	MICHELIN	5
R/H Rear Tyre	225/45 R17	MICHELIN	5
L/H Rear Tyre	225/45 R17	MICHELIN	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

5. General Information

Accident Date	21/09/2024	Inspection Date	24/09/2024 (14:28)
Survey held at	YAP AUTO SERVICE 9004 TAMPINESE STREET 93,#01-78,TAMPINESE INDUSTRIAL PARK A, SINGAPORE 528838		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.