


PHOTOGRAPHS FOR VEHICLE NO. : SMW 5889U



PHOTOGRAPHS FOR VEHICLE NO. : SMW 5889U



PHOTOGRAPHS FOR VEHICLE NO. : SMW 5889U



PHOTOGRAPHS FOR VEHICLE NO. : SMW 5889U





PHOTOGRAPHS FOR VEHICLE NO. : SMW 5889U



PHOTOGRAPHS FOR VEHICLE NO. : SMW 5889U



PHOTOGRAPHS FOR VEHICLE NO. : SMW 5889U



PHOTOGRAPHS FOR VEHICLE NO. : SMW 5889U







LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 9 of 12)



PHOTOGRAPHS FOR VEHICLE NO. : SMW 5889U



PHOTOGRAPHS FOR VEHICLE NO. : SMW 5889U



PHOTOGRAPHS FOR VEHICLE NO. : SMW 5889U



PHOTOGRAPHS FOR VEHICLE NO. : SMW 5889U

