

# Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : SMD 3275D

Date: 15.02.2024

S/N	Parts Description	Unit Price	Amt
1	Rear bumper assy	\$762.70	X
2	Rear bumper side RH	\$185.60	X
3	Rear fender protector RH	\$199.00	✓
4	Rear door RH	\$930.60	X
	Special Nett		
1	Rear bumper clips	\$60.00	X
2	Rear door protector RH	\$120.00	Pass

20%

## Labour

1	To remove and refit damaged parts, cut/weld damaged areas.	\$600.00	20%
2	To spray paint on affected areas.	\$700.00	\$00
3	Check wiring	\$60.00	X
4	Tuff coating	\$150.00	X
		<hr/>	
		\$1,510.00	

NOT Authorized  
L1 Reg & 75ch  
Pulung After Paint

2 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: