



# Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : SMD 3275D

Date: 15.02.2024

S/N	Parts Description	Unit Price	Amt
1	Rear bumper assy		<i>Sm</i> \$762.70 <i>X</i>
2	Rear bumper side RH		<i>n</i> \$185.60 <i>X</i>
3	Rear fender protector RH		<i>nd/wr</i> \$199.00 <i>✓</i>
4	Rear door RH		<i>n</i> \$930.60 <i>X</i>
	Special Nett		
		<i>20%</i>	
1	Rear bumper clips		<i>nr</i> \$60.00 <i>X</i>
2	Rear door protector RH		<i>na</i> \$120.00 <i>part</i>

## Labour

1	To remove and refit damaged parts, cut/weld damaged areas.	\$600.00	<i>20%</i>
2	To spray paint on affected areas.	\$700.00	<i>Food</i>
3	Check wiring	<i>nr</i> \$60.00	<i>X</i>
4	Tuff coating	<i>nr</i> \$150.00	<i>X</i>
			<hr/>
			\$1,510.00

*NOT Authorized  
L1 by 875ch  
Review After Paint*

*2 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: