

ASS. REC. BY:

REF: C72 /Hennerh

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: R 157K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 09 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: SND 6525BYr Regn: 01, 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy

(A)

NuraC.C. 1797Colour M. SilverSp. Reading 222988

AC: Insured / Std / NI / NA

Eng/No: _____

T/Radio: Insured / Std / NI / NA

C/No: _____

ZWR 80 . 0506389Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: _____

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Davanti

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 20/9/24D.O.I. 24/9/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

o/s Rear body

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

S - RS. \$ _____

☐

: Interview (\$ _____)

: Fines _____

☐

: Tech Invs (\$ _____)

: Others _____

☐

: Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 23/09/24
VEHICLE : SND6525B
MAKE/MODEL : TOYOTA / NOAH
CHASSIS NO : ZWR80-0506389
MILLAGE :
TYRE SIZE : 195/65R15
DOA : 20/09/24

*Not Notified
1/10/24
Resurvey After Rain
4 days*

LIST ITEM

01 PC REAR RH FENDER
01 PC REAR RH FENDER INNER SHEILD
01 PC REAR RH MUDFLAT
01 PC REAR RH FENDER INNER TRIM BOARD
01 PC REAR AIR COND BLOWER BOX ASSY
01 PC REAR RH DOOR
01 PC REAR RH DOOR WEATERSTRIP
01 PC REAR RH DOOR INNER TRIM BOARD
01 PC REAR RH DOOR STEP GANISH
01 PC REAR RH DOOR POWER MOTOR ASSY
01 PC REAR RH ROCKER PANEL *Paintish*
01 PC REAR RH WHEEL BEARING
01 PC REAR RH ABSORBER

25!

R	\$	2,041.77	X
SW	\$	368.50	X
R	\$	256.30	X
SW	\$	848.91	X
SW	\$	2,565.45	X
R	\$	1,990.56	✓
	\$	395.20	✓
R	\$	2,147.88	X
CM	\$	442.74	✓
	\$	3,562.10	✓
CM	\$	720.48	X
SW	\$	380.60	X
SW	\$	521.60	X
	\$	16,242.09	

Special Nett

10 PC INNER TRIM BOARD CLIP @ \$8.00
01 PC REAR RH RIM
01 PC REAR RH TYRES
01 PC GLASS SEALANT

R	\$	80.00	X
	\$	1,200.00	✓
R	\$	250.00	X
SW	\$	100.00	X
	\$	1,630.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECTED AREA
3. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS
4. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL
5. TO SUPPLY LABOUR TO CONDUCT WHEEL BALANCING
6. TO SUPPLY LABOUR TO CONDUCT WHEEL ALIGMENT
7. TO SUPPLY LABOUR TO DISMANTLE FENDER INNER UPHOLSTER
8. TO SUPPLY LABOUR TO REFILL AIR COND GAS
9. TO SUPPLY LABOUR TO DISMANTLE & REFIX REAR FENDER GLASS

\$	2,000.00	4501
\$	900.00	8001
\$	200.00	201
\$	250.00	301
\$	50.00	X
\$	150.00	601
\$	300.00	X
\$	120.00	X
\$	300.00	X
	4,270.00	

TOTAL PARTS
TOTAL SPECIAL NETT
TOTAL LABOUR
TOTAL COST OF REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	16,242.09
\$	1,630.00
\$	4,270.00
	22,142.09