



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0486/2024/EQ
DATE : 21-Jun-24
WIP : 20149

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/6/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR. LEE JUN WEI, ERIC
ADDRESS : BLK 346 CHOA CHU KANG LOOP
#08-77
SINGAPORE 680346
TELEPHONE : HP +65 94594292
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070161277-03
VEHICLE NO : **SMX 3836 E**
MODEL CODE : AUDI A7 SPORTBACK 2.0 TFSI
MODEL YEAR : 29/11/2019
ENGINE NO : DLH 067039
CHASSIS NO : WAUZZZF21LN013368
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Jun-24
PLACE OF ACCIDENT : 167, JALAN EMAS 7 , TAMAN IMPIAN EMAS
81300 JOHOR BAHRU, JOHOR, MALAYSIA

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 3836 E.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER - LH <i>H/</i>	1	\$ 2,163.00	
2	FRONT FENDER BRACE - LH <i>X</i>	1	\$ 193.00	
3	FRONT FENDER BRACKET - LH UPPER <i>X</i>	1	\$ 55.00	
4	FRONT FENDER CLOSING ELEMENT - LH <i>?</i>	1	\$ 72.00	
5	FRONT FENDER ATTACHMENT PARTS - LH <i>X</i>	1	\$ 94.00	
6	FRONT WHEEL HOUSING LINER - LH <i>?</i>	1	\$ 332.00	
7	FRONT WHEEL SPOILER - LH <i>X</i>	1	\$ 207.00	
8	WHEEL HOUSING LINER ATTACHMENT PARTS - LH <i>X</i>	1	\$ 82.00	
9	FRONT FENDER LOWER BRACKET - LH <i>X</i>	1	\$ 34.00	
10	FRONT FENDER LOWER BRACKET SUPPORT - LH <i>X</i>	1	\$ 8.00	
11	SIDE MEMBER ATTACHMENT PARTS - LH <i>X</i>	1	\$ 153.00	
12	SIDE MEMBER ADHESIVE TAPES - LH <i>X</i>	1	\$ 69.00	
13	FRONT DOOR - LH <i>H/</i>	1	\$ 5,395.00	
14	FRONT DOOR CATCH - LH <i>?</i>	1	\$ 160.00	
15	FRONT DOOR SEAL, OUTER - LH <i>new</i>	1	\$ 275.00	
16	FRONT DOOR RETAINING STRIP OUTER SEAL - LH <i>new</i>	1	\$ 9.00	
17	FRONT DOOR HINGE - LH UPPER / LOWER <i>?</i>	2	\$ 264.00	
18	FRONT DOOR ATTACHMENT PARTS - LH <i>X</i>	1	\$ 390.00	
19	FRONT DOOR CORNER TRIM - LH <i>X</i>	1	\$ 97.00	
20	FRONT DOOR SEALING ELEMENT - LH <i>X</i>	1	\$ 22.00	
SUB TOTAL SPARE PARTS		:	\$ 10,074.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 3836 E.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT DOOR SEALING ELEMENT - LH X	1	\$	22.00
22	FRONT DOOR WINDOW APERTURE SEAL - LH INNER X	1	\$	570.00
23	FRONT WINDOW SLOT SEAL - LH OUTER?	1	\$	398.00
24	FRONT DOOR WINDOW - LH sca/	1	\$	439.00
25	FRONT WING MIRROR GLASS - LH ms/	1	\$	1,437.00
26	FRONT WING MIRROR CAP - LH cm/	1	\$	392.00
27	FRONT WING MIRROR MOUNT - LH bro/	1	\$	3,385.00
28	FRONT DOOR HANDLE - LH sca/	1	\$	521.00
29	FRONT DOOR HANDLE CAP - LH sca/	1	\$	116.00
30	FRONT DOOR HANDLE UNDERLAY - LH INNER / OUTER X	2	\$	15.00
31	FRONT DOOR MOUNTING BAR ?	1	\$	203.00
32	REAR DOOR - LH st/	1	\$	5,395.00
33	REAR DOOR CATCH - LH ?	1	\$	160.00
34	REAR DOOR SEAL, OUTER - LH ms/	1	\$	275.00
35	REAR DOOR RETAINING STRIP - LH ms/	1	\$	6.00
36	STONE CHIP FILM FOR SIDE MEMBER X	1	\$	249.00
37	REAR DOOR HINGER - LH UPPER / LOWER ?	1	\$	131.00
38	REAR DOOR HINGER - LH LOWER ?	1	\$	193.00
39	REAR DOOR ATTACHMENT PARTS X	1	\$	390.00
40	CHROME ROOF MOLDING - LH de/	1	\$	887.00
41	FRONT TYRE - LH X	1		TBC
42	REAR TYRE - LH X	1		TBC
43	SUNDRIES	1	\$	600.00
TOTAL SPARE PARTS		:	\$	25,858.00
TOTAL LABOUR CHARGES		:	\$	9,932.00
GRAND TOTAL		:	\$	35,790.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 3836 E.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$ 480.00	X
2	TO REMOVE AND TRANSFER LHS FRONT REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00	/
3	TO REMOVE AND REINSTALL FRONT BUMPER AND LHS SILL PANEL TRIM. TO DISMANTLE AND RENEW LHS FRONT FENDER AND LHS FRONT AND REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,000.00	2000
4	TO RESPRAY LHS FRONT AND REAR DOOR, LHS FRONT FENDER, LHS FRONT AND REAR DOOR HANDLES AND LHS WING MIRROR.	\$ 3,800.00	2350
5	TO RENEW LHS FRONT AND REAR RIM. TO CARRY OUT WHEEL ALIGNMENT.	S/N \$ 560.00	280
6	TO SUPPLY AND REINSTALL PAINT PROTECTION FILM ON FENDER AND WING MIRROR COVER	S/N TBC	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00	/
TOTAL LABOUR CHARGES		: \$ 9,932.00	

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Rasul - Hp 90010068
: 24/06/24
: 6 days
: Excess: TBA
: Repair / Rep 59 part

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT