



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLC 7709 K

S/N	NATURE OF JOBS			ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW BACK VEHICLE FROM ACCIDENT SCENE	S/N	\$	280.00	Xnn
2	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N	\$	480.00	/
3	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N	\$	450.00	?X17
4	TO REMOVE AND RENEW LHS ADDITIONAL RADIATOR.	S/N	\$	/ 880.00	/
5	TO CARRY OUT VACUUM AND REGAS R1234.	S/N	\$		/
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$	2,79%.00	600/
7	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS.		\$	3,800.00	1900/
8	TO RENEW LHS FRONT RIM WITH TYRE AND CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N	\$	520.00	280/
8	TO CARRY OUT FRONT CAMERA CALIBRATION AND ADAPTATION.	5/N	s	480.00	Xnn
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$	/ 292.00	/
	TOTAL LABOUR CHARGES		\$	11,082.00	



SS UBI ROAD 1, SINGAPORE 408699
1EL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 7709 K.

DAM	AGED	PARTS	& P	RICES
	MULU		Charles Co.	111-

S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
1	FRONT BUMPER Torn	1	\$	3,254.00	2603.20
2	FRONT BUMPER FIXING PARTS XAM	1	\$	503.00	
3	FRONT BUMPER AIR GUIDE	1	s	84.00	66.96
4	FRONT BUMPER CLOSING - UPPER CENTRE 7 X3VL	1	s	347.00	
5	FRONT BUMPER GRILLE " XSIC	1	s	258.00	
6	FRONT BUMPER UNDERRUN BAR 7 KSVL Cra	1	s	1,011.00	808.80
7	FRONT BUMPER CLOSING ELEMENT	1	\$	263.00	210.40
8	FRONT BUMPER CLOSING ELEMENT CA	2	s		210:40
9	RADIATOR GRILLE ? YSUL	1	\$	3,039.00	
10		1	s	374.00	298.80
11	FRONT PARKING AID SENSOR MIS	1	\$		228.80
12	FRONT PARKING AID SENSOR SEAL RING	4	5		8.64
13	FRONT BUMPER WIRING SET X17	1	5	751.00	
14	LED HEADLIGHT - LH ? HIV	1	5	11,979.00	
15	LIFT CYLINDER - LH CW/	1	s	238.00	190.40
16	LIFT CYLINDER HOSE - LH CA	1	s		99120
17	FRONT FENDER - LH THEY	1	S	2,043.00	
18	FRONT FENDER ATTACHMENT PARTS - LH X 1	1	\$	138.00	
19	FRONT FENDER BRACKET - LH X 17	1	\$	76.00	
20	FRONT FENDER BRACKET - LH X 1 1	1	\$	80.00	
	SUB TOTAL SPARE PARTS		\$	25,385.00	
	ALL CHARGES ARE NOT INCLUSIVE OF ACT				

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

SS UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 7709 K.

DAMA	GED	PARTS	& P	RICES
------	-----	-------	-----	-------

S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
				210.00	
21	FRONT FENDER BRACE - LH XAM,	1	5		20120
22	FRONT WHEEL HOUSING LINER - LH TOM	1	\$		231.20
23	FRONT WHEEL HOUSING LINER ATTACHMENT - LH XA	1	\$	206.00	. 2 20
24	FRONT WHEEL SPOILER - LH OUTER CM	1	\$		43.92
25	FRONT WHEEL SPOILER - LH INNER CM	1	\$	72.00	57.36
26	FRONT WHEEL ARCH COVER - LH / RH 🖊	2	5	1,548.00	1237.60
27	ADDITIONAL RADIATOR 4	1	5	1,076.00	860.80
28	ADDITIONAL RADIATOR BRACKET M	1	\$	170.00	
29	ADDITIONAL RADIATOR AIR GUIDE COV	1	\$	62.00	49.36
30		6	5	332.00	265:44
31	and the second second is the second s	1	5	392.00	314
32	REFRIGENT LINE 4/	1	\$	281.00	224,80
33	REFRIGENT LINE KM	1.	\$	341.00	
34	HORN $ mathcal{1} mathcal{1} mathcal{2} mathcal{3} mathcal{4} math$	1	5	270.00	
35	FRONT NO PLATE X	S/N	\$	60.00	
36	FRONT RIM - LHS A	1		PRICE TBA	
37	FRONT TYRE - LHS cut	1	\$	520.00	1
38	SUNDRIES ? New /		\$	600.00	31168
	TOTAL SPARE PARTS		\$	31,869.00	
	TOTAL LABOUR CHARGES	:	\$	11,082.00	
	GRAND TOTAL		\$	42,951.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINCAPORE 408699 TEL: 6366 2323 FAX: 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST LIABILITY

REMARKS

: RASUL - Hp90010068 : 25/09/24 : 5 dup : Penna : EXESS : 7BA Peny by paind

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY, PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO **BODY REPAIR MANAGER** ALLAN WU **CLAIMS CONSULTANT**