

Name & Address:

**Motor Claims Department**  
**INDIA INTERNATIONAL INSURANCE P/L**  
 64 CECIL STREET  
 #04-#05 IOB BUILDING  
 SINGAPORE 049711

Email/Fax No:

Contact No:

Type of Claim:

THIRD PARTY

YEAR MODEL:

11/12/2020

Vehicle No:

**SMW2704P**

Brand & Model:

MERCEDES BENZ / GLA180 URBAN

Chassis/VIN No:

**WDC1569422J688791**

WIP#:

*not allowed in may 25/9/24*  
*4 days*  
*plp #6660-90*

**REPAIR ESTIMATE**

Date: 23-Sep-24

Franchise: MERCEDES

Contact Person (Eurokars):

WONG

Contact No (Eurokars):

6331 0680

**PARTS / MATERIAL CHARGES**

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT FENDER LH		1		-	\$ 1,070.00
2	FRONT FENDER ARCH GARNISH LH		1		-	\$ 289.00
3	FRONT FENDER UNDERSHIELD LH		1		-	\$ 305.00
4	FRONT FENDER UNDERSHIELD CLIPS		10		-	\$ 50.00
5	FRONT DOOR LH		1		-	\$ 2,325.00
6	FRONT DOOR HINGE LH UPPER		1		-	\$ 265.00
7	FRONT DOOR HINGE LH LOWER		1		-	\$ 175.00
8	FRONT DOOR CHECKER LH		1		-	\$ -
9	SIDE SKIRT LH		1		-	\$ 445.00
10	FRONT SHOCK ABCORBER LH		1		-	\$ 1,068.00
11	FRONT SHOCK ABSORBER MOUNTING LH		1		-	\$ 384.00
12	FRONT KNUCKLE ARM LH		1		-	\$ 1,176.00
13	FRONT WHEEL BEARING LH		1		-	\$ 240.00
14	FRONT LOWER ARM LH		1		-	\$ 840.00
15	STEERING GEAR		1		-	\$ 6,648.00
16	TIE ROD END LH		1		-	\$ 112.00
17	FRONT RIM LH		1		-	\$ 1,344.00
18						\$ -

*parts discard. 10%*

Sub-Total (Parts Price) \$ - \$ 16,736.00

**LABOUR / SERVICES CHARGES**

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE FRONT FENDER LH, FRONT DOOR LH, SIDE SKIRT LH & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR A-PILLAR LH & ALL AREAS AFFECTED BY THE ACCIDENT.	700	\$ 2,400.00
2	TO RESPRAY FRONT FENDER LH, FRONT DOOR LH	600	\$ 2,000.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	30	\$ 250.00
4	TO REMOVE & REPLACE THE FRONT LH UNDER CARRIAGE INCLUDING STEERING GEAR	nett	\$ 1,200.00
5	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.	nett	\$ 120.00

6	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	280	nett	\$	560.00
7	TO TRANSFER THE FRONT DOOR LH MECHANISM.	80	nett	\$	300.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120		\$	250.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	nett	\$	500.00
10	SUNDRIES.	net 20	nett	\$	50.00

Survey Date & Time:	Repair Days:	Excess:
---------------------	--------------	---------

Surveyor Remarks:

**Remarks:**

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ - \$ 7,630.00

	REVISED	PRICE
Parts Price	\$ -	\$ 16,736.00
Labour Price	\$ -	\$ 7,630.00
Total (Initial Estimate)	\$ -	\$ 24,366.00
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 24,366.00
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 24,366.00
GST 9%	\$ -	\$ 2,192.94
<b>GRAND TOTAL</b>	\$ -	\$ 26,558.94

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, pending resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

7-5201  
102  
4680-90  
6660-90

Name & Address:

**Motor Claims Department**  
**INDIA INTERNATIONAL INSURANCE P/L**  
 64 CECIL STREET  
 #04-#05 IOB BUILDING  
 SINGAPORE 049711

Email/Fax No:

Contact No:

Type of Claim:

THIRD PARTY

Policy No:

44147

Vehicle No:

**SMW2704P**

Brand & Model:

MERCEDES BENZ / GLA180 URBAN

Chassis/VIN No:

**WDC1569422J688791**

Mileage:

Date:

22-Oct-24

Franchise:

MERCEDES

Contact Person (Eurokars):

WONG

Contact No (Eurokars):

6331 0680

**PARTS / MATERIAL CHARGES**

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT FENDER INNER GARNISH LH		1		- Torn	\$ 62.00
2	FRONT FENDER INNER GARNISH CLIPS		4		- new	\$ 36.00
3	SIDE SKIRT LH CLIPS		6		- new	\$ 54.00
4	WINDSCREEN GARNISH BRACKET		4		- Torn	\$ 52.00
5	SIDE SKIRT BOTTOM CLIPS		6		- new	\$ 54.00
6	FRONT DOOR SEAL LH <i>rubber</i>		1		- new	\$ 360.00
7	FRONT DOOR RIVET		11		- new	\$ 99.00
8						\$ -

Sub-Total (Parts Price) \$ - \$ 717.00

**LABOUR / SERVICES CHARGES**

NO	DESCRIPTION	REVISED	PRICE

Survey Date & Time:

Repair Days:

Sub-Total (Labour Price) \$ - \$ -

Surveyor Remarks:

Parts Price \$ - \$ 717.00  
 Labour Price \$ - \$ -  
 Total (Supp 1) \$ - \$ 717.00