



BAN HOCK HIN
Co., Pte Ltd

Fadhli
3030
Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

Step (LKK) 24/9/24, 1.30p

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MS FIRST CAPITAL INSURANCE LTD

QUOTATION

NO. : 47747

DATE : 21/09/2024
CLAIM NO. : 12597
POLICY NO. : MC00884209/03

FROM : STEPHANIE

VEHICLE NO. : FBM9515E
MAKE/MODEL : YAM / SNIPER T150

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY - (REPORTED BY MECHANIC)	Repair	1.00	\$540.00	540.00
2	AXLE WHEEL FRONT / Bj P/N: 57081 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00 /
3	BALANCER HANDLE SET (RCB) / RV - (REPORTED BY MECHANIC)	REPLACE	1.00	\$75.00	75.00 /
4	BASKET SNIPER150 / BT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	71.00 /
5	BOX REAR (GIVI) E43N / RV P/N: 63891 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$373.00	373.00 /
6	BRACKET MASTER PUMP RH / BR P/N: 72530 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	11.00 /
7	BRACKET SIDE COVER / ST - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00 /
8	BRACKET TANK RESERVOIR / BT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00 /
9	COOLANT (MOBIL) ANTIFREEZE / RV P/N: 60213 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00 /



DATA PROTECTION
ASSURED

bizSAFE₃



Blk 8 Defu South Street 1, #04-28, JTC Defu Industrial City, Singapore 533758 | Tel: +65 6281 6520 | www.bhh.com.sg
Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) + 65 6281 6750

CERT NO: 2022-1-0343
EO 1961-2015

S/N	Description	Action	Qty	Unit Price	Amount
10	COVER CRANKCASE 1 P/N: 72007 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$155.00	155.00 ✓
11	COVER FRONT LOWER LH P/N: 57070 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00 ✓
12	COVER FRONT LOWER RH P/N: 57072 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00 ✓
13	COVER SET BLACK METALLI X (V1) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$481.00	481.00 ✓
14	EMBLEM PANEL FRONT P/N: 64172 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00 ✓
15	FOOTREST FRONT LH P/N: 39116 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	23.00 ✓
16	FOOTREST REAR LH P/N: 72015 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00 ✓
17	FRONT FORK ASSY P/N: 71360 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$505.00	505.00 ✓
18	FRONT SIGNAL LIGHT ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00 ✓
19	GASKET CRANKCASE COVER 1 P/N: 57244 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00 ✓
20	GUIDE AIR 1 P/N: 57082 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00 ✓
21	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	20.00 16	\$85.00 / 55	1,700.00 1100 880
22	LEVER BRAKE RH P/N: 69244 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00 ✓
23	LEVER CLUTCH P/N: 63058 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00	25.00 ✓
24	LIGHT PILOT FRONT P/N: 57053 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$172.00	172.00 ✓



S/N	Description	Action	Qty	Unit Price	Amount
25	MIRROR LH / CM7 P/N: 58099 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00 /
26	MIRROR RH / MW P/N: 58187 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00 /
27	OBV TYPE B (12V) NEW / CM7 P/N: 82490 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	341.00 /
28	OIL ENGINE (MOBIL) ADVANCE RACING 1 10/40 / M1 P/N: 72811 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$41.00	41.00 /
29	O-RING / MC P/N: 72002 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	5.00 /
30	PANEL INNER FRONT HEADLAMP / BR P/N: 57075 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00 /
31	PANEL STAND COVER BIG / CRU P/N: 57058 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00 /
32	PEDAL GEAR ASSY / BT P/N: 71365 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	23.00 /
33	RADIATOR COMP / BT P/N: 73072 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$171.00	171.00 /
34	RUBBER FOOTREST FRONT / CM7 P/N: 36394 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00 /
35	RUBBER PEDAL GEAR / CM7 P/N: 63062 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	8.00 /
36	STAY (P/N: 72188) ? / BT P/N: 72188 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00 /
37	STEERING CONE SET / MC P/N: 33765 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$54.00	54.00 /

SUB TOTAL

GST @ 9 %

GRAND TOTAL (SGD)

\$5,188.00

\$466.92

\$5,654.92

50% deposit required before ordering of parts.

Valid KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

bizSAFE₃

Blok 6 Defu South Street 1, #04-28, JTC Defu Industrial Ctr., Singapore 533758 | Tel: +65 6281 6520 | www.bhh.com.sg
 Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) + 65 6284 2969, (Accounts) + 65 6281 6759

CLAT NO. 2882 1-0000
 ISO 9001:2015