



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24090421/Eqp3e2
16 RAFFLES QUAY	Date:	25/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 1313R	Veh. Inspected	FBM 9515E
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24008124MFCT	Excess	\$0.00
Assign From	BETTY	Assign Date	24/09/2024

2. Vehicle Details

Make & Model	YAMAHA SNIPER T150	C.C	150
Engine No.	G3E6E0384657	Year of Reg.	22/05/2018
Chassis No.	MH3UG0740J0101693	Colour	BLACK
Odometer	67380 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	90/80-17	PIRELLI	5
L/H Front Tyre			
R/H Rear Tyre	120/70-17	PIRELLI	5
L/H Rear Tyre			

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/09/2024	Inspection Date	24/09/2024
Survey held at	BAN HOCK HIN CO.PTE LTD - BLK 8 DEFU SOUTH STREET 1, #04-28 JTC DEFU INDUSTRIAL CITY, SINGAPORE 533758		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days