Our Ref: GBL647Y240920		Date: 20/10/2024
Your Ref:		
India International Insurance Pte Ltd 64 Cecil Street #04-00 & #05-00 IOB Building Singapore 049711 Motor Claims Department		
Dear Sir / Madam		
Traffic Accident Along Tai Seng Street Involving GBL647Y and SLX3365J On 20/09/20	024	
We/I, <u>Goldbell Leasing Pte Ltd</u> (NRIC / ROC No: m/vehicle - <u>GBL647Y</u> at all material times of the aby " <u>India Int'nl</u> " authorized appraiser and we/I bas for S\$ 8,066-00 (w/GST) being the repair for <u>10</u> Days (S	above accident. Ou ed our/my claims	ur/my vehicle was surveyed s on his recommendation
We/I have ascertained that you were the insurers of the disame was involved in the aforesaid accident with our/my	•	
We/I whereby you are the insurers of m/vehicle <u>SLX336</u> : solely by the negligence of your insured and as a result the has suffered loss and damage as follows:		
Cost of repairs	S\$	8,066-00 (w/GST)
LOU for pre-repair notice 02 days @ S\$ 90-00 [2982 cc]	54	180-00
LOU Fee for10days @S\$ _90-00 [2982 cc]		900-00
Rental Fee Invoice No:		2-18
GIA / LTA search fee		65-00
Towing Fee (Cash Sale No) Survey Fee		
Total Amount	S\$	9,213-18
We/I enclose herewith copies of the supporting document (i) Motor Accident Report & Documents; (ii) Repair Invoices;	ts for vehicle no	GBL647Y as follows:-
Kindly look into the matter and let us/me hear from you as possible.	on the settlemen	t of our/my claims as soon
Please remit us/me your settlement sum in favor of M/s		

Yours faithfully,

√	_	
The owner of m/vehicle	GBL647Y	
Messers <u>Goldbell Leasing</u>	<u>Pte Ltd</u>	
cc. Liu's Bro Auto Works	shop	

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

FINAL BILL

Tel: 67411730

20/10/2024

Name: India International Insurance Pte Ltd

Address Motor Claims Department

64 Cecil Street #04-00 & #05-00

IOB Building Singapore 049711

Ref Date: Ref No:


GBL647Y240920 GBL647Y

Vehicle No: GBL647Y Model / Make: Toyota Hiace

Capacity: 2982 cc Van Turbo 4 DR AT

Item #	Damaged Area	Description	Uı	nit Price	Qty		imation / uotation	N / SN	ost Of Lepair
1	Rear	Tailgate	\$ 2	2,759.10	1	\$:	2,759.10		\$ -
2		"Toyota" Motif	\$	82.60	1	\$	82.60		\$ -
3		Tailgate Lock	\$	399.20	1	\$	399.20		\$ -
4		Tailgate Weatherstrip	\$	388.50	1	\$	388.50		\$ -
5		Bumper	\$	681.40	1	\$	681.40		\$ -
6		Bumper Clips 1 set	\$	65.00	1	\$	65.00	SN	\$ -
7		Bumper Reverse Sensor	\$	220.00	1	\$	220.00	SN	\$ -
8	Rear Rh	Bumper Side Holder	\$	66.50	1	\$	66.50		\$ -
9		Bumper Lower Bracket	\$	32.80	1	\$	32.80		\$ -
10		Tail Lamp	\$	408.20	1	\$	408.20		\$ -
11		Tail Lamp Lower Garnish	\$	161.80	1	\$	161.80		\$ -
12		Tail Lamp Lower Garnish Bracket	\$	60.80	1	\$	60.80		\$ -
13		Tail Lamp Housing Panel	\$	728.20	1	\$	728.20		\$ -
14		Tail Lamp Inner Housing Panel	\$	455.80	1	\$	455.80		\$ -
15		Fender (Body Panel)	\$ 2	2,039.20	1	\$:	2,039.20		\$ -
16		Fender Inner Panel	\$	1,655.30	1	\$	1,655.30		\$ -
17		Air Vent	\$	48.60	1	\$	48.60		\$ -
18		Exhaust	\$	850.80	1	\$	850.80		\$ -
19		Fender Inner Trim Board	\$	248.20	1	\$	248.20		\$ -
20		End Panel Inner	\$	936.20	1	\$	936.20		\$ -
21		End Panel Outer	\$	566.10	1	\$	566.10		\$ -
22		End Panel Top Steel Plate	\$	211.80	1	\$	211.80		\$ -
23		End Panel Sealant	\$	50.00	1	\$	50.00	SN	\$ -
24		Tailgate "70 KM/H" Sticker	\$	15.00	1	\$	15.00	SN	\$ -
25		Tailgate "8 PAX" Sticker	\$	15.00	1	\$	15.00	SN	\$ -
26		Tailgate Windscreen Sealant	\$	50.00	1	\$	50.00	SN	\$ -
		C/F Balance>				\$ 1	13,196.10		\$ -





No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN & GST No: 42674600K liusbro@ymail.com Tel: 67411730

FINAL BILL

20/10/2024

Name: India International Insurance Pte Ltd Ref Date: Ref No:

GBL647Y240920 Address Motor Claims Department

GBL647Y 64 Cecil Street #04-00 & #05-00 Vehicle No:

Toyota Hiace **IOB** Building Singapore 049711 Model / Make:

> Van Turbo 4 DR AT 2982 cc Capacity:

B/F Balance> \$ 13,196.1 27		I		Capacity:	2502	1		IDO 4 DRAI
Rear Tailgate "Corporate" Advertisement & \$ 450.00 Rear Fender "Corporate" Advertisement & \$ 680.00 To check all wiring & electrical component for proper function Remove and refix rear bumper reverse sensor Remove & reinstall Tailgate Windscreen Glass to facilitate repairs Remove and refix rear tailgate components & \$ 120.00 Remove and refix rear tailgate components & \$ 100.00 Remove and replace rear exhaust pipe system to facilitate repairs Labor for Panel Beating, Cut, Weld, Straighten & \$ 1,800.00 Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affecteed areas To apply Rust Proofing , reseal tuff-coating treatment on accident area Total Parts & Labour of estimate for damaged vehicle Sub-Total \$ 18,176.1	Item #		Description	Unit Price	Qty	Estimation / Quotation	N/ SN	Cost Of Repair
Artwork Rear Fender "Corporate" Advertisement & \$680.0 To check all wiring & electrical component for proper function Remove and refix rear bumper reverse sensor Remove & reinstall Tailgate Windscreen Glass to facilitate repairs Remove and refix rear tailgate components & \$100.00 Remove and refix rear tailgate components & \$100.00 Remove and replace rear exhaust pipe system to faciltate repairs Remove and replace rear exhaust pipe system to faciltate repairs Labor for Panel Beating, Cut, Weld, Straighten & \$1,800.00 Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affecteed areas To apply Rust Proofing, reseal tuff-coating treatment on accident area Total Parts & Labour of estimate for damaged vehicle Sub-Total 5 18,176.12			B/F Balance>			\$ 13,196.10		\$ -
Artwork Rear Fender "Corporate" Advertisement & \$680.0 To check all wiring & electrical component for proper function Remove and refix rear bumper reverse sensor Remove & reinstall Tailgate Windscreen Glass to facilitate repairs Remove and refix rear tailgate components & \$100.00 Remove and refix rear tailgate components & \$100.00 Remove and replace rear exhaust pipe system to faciltate repairs Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affecteed areas To apply Rust Proofing, reseal tuff-coating treatment on accident area Total Parts & Labour of estimate for damaged vehicle Total amount in Lumpsum Basis for repaired vehicle								
Artwork To check all wiring & electrical component for proper function Remove and refix rear bumper reverse sensor Remove & reinstall Tailgate Windscreen Glass to facilitate repairs Remove and refix rear tailgate components & s 120.00 Remove and refix rear tailgate components & s 100.00 Remove and replace rear exhaust pipe system to facilitate repairs Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affected areas To apply Rust Proofing, reseal tuff-coating treatment on accident area Total Parts & Labour of estimate for damaged vehicle Total amount in Lumpsum Basis for repaired vehicle	27					\$ 450.00	SN	\$ -
proper function Remove and refix rear bumper reverse sensor Remove & reinstall Tailgate Windscreen Glass to facilitate repairs Remove and refix rear tailgate components & sensor Remove and refix rear tailgate components & sensor Remove and replace rear exhaust pipe system to facilitate repairs Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affected areas To apply Rust Proofing, reseal tuff-coating treatment on accident area Total Parts & Labour of estimate for damaged vehicle Total amount in Lumpsum Basis for repaired vehicle \$ 100.00 \$ 120.00 \$ 100.00 \$ 100.00 \$ 11,500.00 \$ 100.00 \$ 18,176.10	28		_			\$ 680.00	SN	\$ -
Remove & reinstall Tailgate Windscreen Glass to facilitate repairs Remove and refix rear tailgate components & mechanism Remove and replace rear exhaust pipe system to facilitate repairs Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affected areas To apply Rust Proofing, reseal tuff-coating treatment on accident area Total Parts & Labour of estimate for damaged vehicle Sub-Total \$ 120.00 \$ 100.00 \$ 1,800.00 \$ 1,500.00 \$ 1,500.00 \$ 100.00 \$ 1,500.00 \$	29					\$ 50.00		\$ -
to facilitate repairs Remove and refix rear tailgate components & semechanism Remove and replace rear exhaust pipe system to facilitate repairs Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affected areas To apply Rust Proofing, reseal tuff-coating treatment on accident area Total Parts & Labour of estimate for damaged vehicle Sub-Total \$ 1,20.00 \$ 1,00.00 \$ 1,800.00 \$ 1,500.00 \$ 1,	30		Remove and refix rear bumper reverse sensor			\$ 80.00		\$ -
mechanism Remove and replace rear exhaust pipe system to faciltate repairs Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affected areas To apply Rust Proofing, reseal tuff-coating treatment on accident area Total Parts & Labour of estimate for damaged vehicle Sub-Total \$ 1,800.00 \$ 1,500.00 \$ 1,500.00 \$ 100.00 \$ 1,500.00 \$	31		_			\$ 120.00		\$ -
faciltate repairs Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affecteed areas To apply Rust Proofing, reseal tuff-coating treatment on accident area Total Parts & Labour of estimate for damaged vehicle \$ 1,800.00 \$ 1,500.00 \$ 1,500.00 \$ 100.00 \$ 1,500.00 \$ 100.00 \$ 1,500.00 \$ 100.00 \$ 1,500.00 \$	32					\$ 100.00		\$ -
8 Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affected areas To apply Rust Proofing , reseal tuff-coating treatment on accident area Total Parts & Labour of estimate for damaged vehicle Total amount in Lumpsum Basis for repaired vehicle \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ \$ 1,00.00 \$ \$ 1,00.00 \$ \$ 1,500.00 \$ \$ 1,	33					\$ 100.00		\$ -
36 To apply Rust Proofing , reseal tuff-coating treatment on accident area \$100.00 Total Parts & Labour of estimate for damaged vehicle \$18,176.1	34					\$ 1,800.00		\$ -
Total Parts & Labour of estimate for damaged vehicle Sub-Total Sub-Total \$ 18,176.1	35					\$ 1,500.00		\$ -
Total amount in Lumpsum Basis for repaired vehicle	36					\$ 100.00		\$ -
Total amount in Lumpsum Basis for repaired vehicle								
Total amount in Lumpsum Basis for repaired vehicle								
Total amount in Lumpsum Basis for repaired vehicle								
Total amount in Lumpsum Basis for repaired vehicle								
	Total Pa	arts & Lab	our of estimate for damaged vehicle	Sub-Total		\$ 18,176.10		
GST TAX 9.00% \$ 1,635.8	Total a	mount in L	umpsum Basis for repaired vehicle		1			\$ 7,400.00
	GST TA	AX		9.00%		\$ 1,635.85		\$ 666.00
Grand Total \$ 19,811.9	Grand '	Total			1	\$ 19,811.95		\$ 8,066.00

Eight Thousand Sixty-Six Only SDL w/GST



Liu's Brother Auto Workshop

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SLX3365J

Date of Accident

20/09/2024 苗

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance India International Insurance ...

Period of Insurance 20/09/2023 - 23/09/2024

Requested By Susan Low (Liu's Brother Auto...

Requested Date 23/09/2024 11:31

Payment details
Request Amount: \$\$2
GST Amount: \$\$0.18

Total Amount Due (GST Inclusive): \$\$2.18

General Insurance Association
Records Management Centre
GST Registration No: M400017735

or negistration not in 10021100

1 of 1 23/9/2024, 11:32 am



Co Registration No.53152603L

BILL TO:

Messrs

LIU'S BROTHER AUTO WORKSHOP

Address 1 KAKI BUKIT AVE 6

1-Sep-2024 #01-01 AUTOBAY@KAKI BUKIT 1ST - 30TH SEP'24 Period:

Debit Note No.:

Date:

0859LIU/24

SEPTEMBER SINGAPORE 417883 Month:

1 OF 1 Attention **JASMINE** Page: Tel Payment Terms: COD 9710 1815

S/N	WEEK	DATE	CARPLATE NO	MODEL	WORK ORDER	AMOUNT DUE (\$)
1	38	20-Sep-24	GBL 647 Y	TOYOTA HIACE	262264	\$65.00
PAGE	SUBTO	ΓAL				\$65.00
	ID TOTA					\$65.00
GICI1						Ψ00.00

Early payment would be appreciated. Pls advise us of any discrepancy within 7 days from the invoice date, otherwise the account will be considered as correct. All cheque should be crossed and made payable to "GAO EXPRESS TOWING SERVICES" or PayNow to UEN "53152603L".

ЈЈМ КОЖ

JIM KOH **GAO EXPRESS TOWING SERVICES** **ACKNOWLEDGEMENT**

NAME / SIGNATURE / COMPANY STAMP / DATE

ACKNOWLEDGE BY:

LIU'S BROTHER AUTO WORKSHOP

SINGAPORE AWARD WINNER You Call, We Tow - Fast . Secured . Reliable **Express Towing Services**

Call Received: D9 12 NVS Completed : __ Arrival : 1030 h

47 Pemimpin Halcyon 2 #C01-02 Singapore 577200 Co. Reg. No. 53152603L HP: 900 900 92 Email: jim.koh@hotmail.com Website: http://www.gaoexpresstowing.sg

CASH SALE/WORK ORDER	No. 262264
質號 Messrs:	Jump Start/Changing of battery
車號 Vehicle No: GBL 64イツ 車型 Model No: T HARR	Tyre Replacement Acedent/Breakdown
時間(明夜) Time (day)night): Contact No: つらす 8369	Multi/Basement
Location: 4 (A) SEY 6 YREAR	King Dolly
To: Autobay #01-01	Transport Charge Low Body Kit
Cash \$: よう 其他 Others:	Door Opening Service
Authorised By: Jiw Tow Truck Alos RA19	Collect Doc/Key
注意本公司對所拖之車輛,在進行中如有任何損失或破壞,一概由車主自行負責。	Woodlands and Tuas Checkpoint

Q.

other misdemeanour to your vehicle whilst being towed.

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or