

ESTIMATED ACCIDENT REPAIR COST



TOWER TRANSIT

Co. / GST Reg No. 201419417K

ACCIDENT TIME REPORTED	19:55	BUS REGISTRATION NUMBER	SBS6356K
ACCIDENT DATE	19-Sep-24	BUS TYPE (SD/DD)	SD
BUS CAPTAIN NAME	ABDUL AZIZ BIN MOHD AMIN	BUS ROUTE NO.	
THIRD PARTY CLAIM AGAINST	SMRT	BUS ADVERT (Y/N)	N

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	REAR WINDOW GLASS	1	\$ 1,034.00
2	INTERIOR REAR WINDSCREEN FLAP	1	\$ 847.44
3	INTERIOR REAR WINDSCREEN EDGE GUARD	1	\$ 85.80
4	MERCEDES STAR SELF ADHESIVE	1	\$ 41.29
5	470MMX52MM STICKER FOR MERCEDES BENZ	1	\$ 18.70
6	CITARO STICKER	1	\$ 33.00
7	SIKAFLEX BLACK	4	\$ 140.80
8	GIVE WAY STICKER	1	\$ 55.00
		9% GST	\$ 203.04
		PARTS TOTAL COST	\$ 2,459.08

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- DISMANTLE AND REPLACE ITEM NO :1-8	\$ 5,200.00
SPRAY PAINTING \$640 PER PANEL	9% GST \$ 468.00
LABOUR CHARGES \$650 PER DAY	LABOUR TOTAL COST \$ 5,668.00

SECTION 3 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

		DATE IN	19/Sep/2024
		DATE & TIME SURVEY	
		DATE OUT	
		TOTAL NUMBER OF DAYS	5
BUS TYPE (SD / DD)	SD		
LOSS OF USE COST		\$1,500.00	

SUMMARY	
SECTION NO.	COST
1	\$ 2,459.08
2	\$ 5,668.00
3	\$ 1,500.00
TOTAL	\$ 9,627.08