

DATE : 24.09.2024

TO : **INCOME** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **GBL 146B**  
 CHASSIS : **JTFAT35YX0K216378**  
 MODEL : **TOYOTA DYNA**  
 DATE OF ACCIDENT : 21.09.2024  
 DATE OF REG : 23.02.2021

*Xiao Chan*

**CLAIM DETAIL : PARTS**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR NUMBER PLATE HOLDER <i>New</i>	1	\$ 234.70	\$ 234.70
2	REAR NUMBER PLATE LAMP <i>New</i>	1	\$ 98.40	\$ 98.40
3	TAIL LAMP <i>New</i>	2	\$ 325.30	\$ 650.60
4	TAIL LAMP SUPPORT BRACKET <i>New</i>	2	\$ 245.40	\$ 490.80
5	SPARE TYRE CARRIER <i>New</i>	1	\$ 385.20	\$ 385.20
6	SPARE TYRE CARRIER BRACKET <i>New</i>	1	\$ 98.30	\$ 98.30
7	REAR EXHAUST <i>New</i>	1	\$ 896.70	\$ 896.70
8	REAR EXHAUST BRACKET <i>New</i>	1	\$ 62.60	\$ 62.60
9	REAR EXHAUST MOUNTING <i>New</i>	1	\$ 32.10	\$ 32.10
			TOTAL PRICE	\$ 2,949.40
			LESS 25%	\$ 737.35
			<b>SUB TOTAL PRICE</b>	<b>\$ 2,212.05</b>

SN	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>New</i>	1	\$ 50.00	\$ 50.00
2	REVERSE CAMERA (SET) <i>Brand</i>	1	\$ 480.00	\$ 480.00
3	REVERSE SENSOR (SET) <i>Brand</i>	1	\$ 280.00	\$ 280.00
4	REAR BOX OPEN DOOR (SPECIAL TYPE) (COMPLETE SET) <i>Build</i>	2	\$ 2,800.00	\$ 5,600.00
5	REAR BOX OPEN DOOR HINGE (SPECIAL TYPE) <i>New</i>	4	\$ 160.00	\$ 640.00
6	REAR BOX OPEN DOOR LOCK CATCH (SPECIAL TYP) <i>New</i>	2	\$ 150.00	\$ 300.00
7	REAR BOX OPEN DOOR '70KM/H' <i>New</i>	1	\$ 30.00	\$ 30.00
8	REAR DOOR COMPANY PRINTED STICKER (SET) <i>New</i>	1	\$ 1,200.00	\$ 1,200.00
9	REAR SAFETY BAR (SPECIAL TYPE) <i>Bent</i>	1	\$ 1,200.00	\$ 1,200.00
10	REAR PROTECTOR BAR RUBBER (SPECIAL TYPE) <i>Wt</i>	2	\$ 180.00	\$ 360.00
11	REAR BOX OPEN DOOR FRAME (STANDARD STEEL) (SPECIAL TYP) <i>Dented</i>	1	\$ 4,000.00	\$ 4,000.00
12	SPARE TYRE (BIG) <i>2 the 1st</i>	1	\$ 380.00	\$ 380.00
13	SPARE TYRE (SMALL) <i>new</i>	1	\$ 350.00	\$ 350.00
14	REAR CARGO BED WOODEN CHASSIS (SPECIAL TYP)	2	\$ 1,800.00	\$ 3,600.00

TOTAL \$ 18,470.00

*7835505*

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD , CUT, ADJUST, KNOCK	\$ <del>1,200.00</del>	800
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ <del>1,200.00</del>	800
3	TO LIFT UP CARGO TO CHANGE REAR WOODEN CHASSIS	\$ 800.00	X
4	TRANSFER REAR DOOR MECHANISM	\$ <del>300.00</del>	120
5	To remove reverse sensor and rear camera REAR CHASSIS ALIGNMENT	\$ <del>250.00</del>	100

1420

**TOTAL** \$ 3,750.00

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 20,682.05  
 TOTAL LABOUR COST : \$ 3,750.00  
 TOTAL REPAIR COST : \$ 24,432.05

Adrian L  
 r/s 24/09/24  
 09 Days

total: 9255  
 r/s: 7HK

7HK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: