



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24060179/Rvh3e2
16 RAFFLES QUAY	Date:	21/06/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 2354K	Veh. Inspected	SME 9289U
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24005398MFCT	Excess	\$0.00
Assign From	CAROLINE CABRERA	Assign Date	20/06/2024

2. Vehicle Details

Make & Model	VOLKSWAGEN TOURAN 1.4 TSI CL	C.C	1395
Engine No.	CZD167965	Year of Reg.	23/10/2018
Chassis No.	WVGZZZ1TZKW002349	Colour	GOLD
Odometer	111743 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55 R17	MICHELIN	6
L/H Front Tyre	215/55 R17	MICHELIN	6
R/H Rear Tyre	215/55 R17	MICHELIN	6
L/H Rear Tyre	215/55 R17	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/06/2024	Inspection Date	21/06/2024
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days