

Damage assessment report:

16th Aug 2024

Mr. Goh Mia Song

IC: S0020806Z

HP: 97853282

Bike: Willier Zero 9 Carbon

The abovementioned Bicycle is found damaged/scratched and out of alignment, deemed unsafe to be used in future, and It is beyond repair. Total amount is \$7675.00 The breakdown below,

DEF

- 1. Frameset \$2600.00
- 2. Groupset: Campagnolo Chorus 11 \$2250.00 / &1
- 3. Wheelset: Campagnolo Shamal Ultra \$1400.00
- 4. Pedal: Look Keo 2 Max Carbon Blade \$205.00
- 5. Cockpit: FSA K-Wing Carbon bar, Stem \$450.00
- 6. Saddle: Astute Carbon \$290.00
- 7. Tires: Vittoria Corsa \$160.00
- 8. Specialized S-Work Helmet \$320.00

20% depiccioting

et chapter2cycle-dyah

Ben Cheong

Chapter 2 Cycle Pte Ltd

UEN: 201103127M

451, Ang Mo Klo Ave 10

#01-1761, Singapore 560451

Tel: 64527168

Steve (LKK) 26/9/24, 9.30 am WHI Prejudice

89k 451, Ang Ma Klo Aye 10 W01-1761.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

