



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24090429/Anp3e2
50 RAFFLES PLACE #03-03	Date:	13/12/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 5594D	Veh. Inspected	SMJ 6603P
Policy No.	-	Coverage	0
Claim No.	CMTD2403077/GPL	Excess	\$0.00
Assign From	PAU LOONG	Assign Date	24/09/2024

2. Vehicle Details

Make & Model	HONDA SHUTTLE HYBRID	C.C	1496
Engine No.	LEB7103214	Year of Reg.	14/03/2019
Chassis No.	GP72002406	Colour	BLACK
Odometer	285912 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/55 R15	MICHELIN	6
L/H Front Tyre	195/55 R15	MICHELIN	6
R/H Rear Tyre	195/55 R15	MICHELIN	6
L/H Rear Tyre	195/55 R15	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/09/2024	Inspection Date	24/09/2024
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

5a. Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days