

ASS. REC. BY:

REF:

SMO1

CS/SM024090432/Knp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TP RES/QD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMN 5281A

Yr Regn:

07.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Honda Fit

C.C.

1496

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

676674

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GP5

1338702

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Black hawk

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

23/9/24

D.O.I.

29/11/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rm old down minor

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/11 8737-08 Canhw (Red. \$ 1516.51, 67%).

Date/Time, File Pass to?

☐

Prel. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

1

Resurvey No. of Trlp:

Survey Fee:

Transportation

S + RS. \$

Fees

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 23/09/2024
VEHICLE : SMM5281A
MAKE/MODEL : HYONDA / FIT
CHASSIS NO : GP5-1338702
MILLAGE :
TYRE SIZE :
DOA : 23/09/2024

Not Authorised
Recovery By painting
1 day
@ 737.08

LIST ITEM

01 PC	RH SIDE MIRROR ASSY	752.60	val 1m	\$	1,546.29	2
01 PC	RH SIDE MIRROR COVER		SVC Ptn	\$	157.30	X
				\$	1,703.59	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECTED AREA
3. TO SUPPLY BODY PAINT CERAMIC COATING
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS

\$601	100.00	301
\$601	100.00	
201	300.00	X
\$	50.00	151
\$	550.00	

TOTAL PARTS

\$ 1,703.59

TOTAL LABOUR

\$ 550.00

TOTAL COST OF REPAIR

\$ 2,253.59

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Huey Yon (LKKAuto)

From: Rajes (LKK Auto)
Sent: Thursday, 26 September 2024 12:09 PM
To: Cheng, Jia Yi; assignments; SUR; Huey Yon (LKKAuto)
Subject: RE: LKK/KK : NOTICE OF PRE-REPAIR INSPECTION - CMTD2403081/JYC / OUR REF.: TCL.VV.an.50560.24.jdm - SMM5281A & GBJ6513X ON 23/09/2024 @ 10:00 HRS ALONG 62 NEW UPPER CHANGI ROAD

Dear Jia Yi,

Thank you for the email.

*Our surveyor found the RH side mirror
unable to function when he test at the time of inspection.*

Dear Huey Yon,

Kindly take note.

Best Regards,

Rajes | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheng, Jia Yi <jiayi.cheng@sompo.com.sg>

Sent: Thursday, September 26, 2024 9:53 AM

To: Rajes (LKK Auto) <rajes@lkkauto.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: LKK/KK : NOTICE OF PRE-REPAIR INSPECTION - CMTD2403081/JYC / OUR REF.: TCL.VV.an.50560.24.jdm - SMM5281A & GBJ6513X ON 23/09/2024 @ 10:00 HRS ALONG 62 NEW UPPER CHANGI ROAD

Dear Rajes,

According to our insured, there is no damage on 3rd party side mirror.

Please refer to above attachment.

Thank you.

*Currently working from home



Jia Yi

Claims Division

50 Raffles Place

#03-03 Singapore Land Tower

Singapore 048623

D: +65 6329 5324

T: +65 6461 6555