



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 23/09/2024
VEHICLE : SMM5281A
MAKE/MODEL : HYONDA / FIT
CHASSIS NO : GP5-1338702
MILLAGE :
TYRE SIZE :
DOA : 23/09/2024

Not Authorised
Mummy B4 painting
1 day
@ 737.08

LIST ITEM

01 PC	RH SIDE MIRROR ASSY	752.60	add in	\$	1,546.29	2
01 PC	RH SIDE MIRROR COVER			res	\$	157.30 X
				\$	1,703.59	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$ 100.00	2
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECTED AREA	\$ 100.00	2
3. TO SUPPLY BODY PAINT CERAMIC COATING	\$ 300.00	X
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$ 50.00	15/
	\$ 550.00	

TOTAL PARTS

TOTAL LABOUR

TOTAL COST OF REPAIR

\$ 1,703.59
\$ 550.00
\$ 2,253.59

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: