



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI24090433/Aqp3m4
Date: 04/12/2024
Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1709Y	Veh. Inspected	SLU 6974Y
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24008346MFCT	Excess	\$0.00
Assign From	AINI	Assign Date	24/09/2024

2. Vehicle Details

Make & Model	TOYOTA C-HR	C.C	1797
Engine No.	2ZR8215295	Year of Reg.	11/12/2017
Chassis No.	ZYX102081926	Colour	WHITE
Odometer	132794 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/50R18	KAPSEN	6
L/H Front Tyre	225/50R18	KAPSEN	6
R/H Rear Tyre	225/50R18	KAPSEN	6
L/H Rear Tyre	225/50R18	KAPSEN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/09/2024	Inspection Date	25/09/2024
Survey held at	AUTOMOBILE HUB ENTERPRISE - 1 KAKI BUKIT AVENUE 6 #01-15 AUTOBAY, SINGAPORE 417883		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days