

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SKV29Y

Not Authorized
C/Ping 84850h
Assembly After Rainy
5 days

No.	Qty	List Items	
1	1	Rear bumper top	\$ Bu 924.10 ✓
2	1	Rear bumper bottom (Black)	\$ Del/LM 479.60 ✓
3	2	Rear bumper side reflector	\$ Bu 183.60 X
4	1-2	Rear bumper reverse sensor 0481-90	\$ Bu 1,298.40 ✓
5	2	Rear bumper side retainer	\$ Bu 105.40 X
6	1 set	Rear bumper clips	\$ Bu 60.00 ✓
7	1	Rear bumper inner foam	\$ CM 154.70 ✓
8	1	Rear tailgate 67005-48350	\$ Bu 2,827.60 ✓
9	1	Rear tailgate LH "HARRIER" emblem	\$ Bu 84.90 ✓
10	1	Rear end panel 58307-48120	\$ Bu 1,260.70 ✓
11	1	Rear RH lower exhaust silencer	\$ Bu 2,381.80 X
			\$ 9,760.80
Less 25%			\$ 2,440.20
Total :			\$ 7,320.60

Special Nett Items		
12	1 set	Rear end panel sealant
		\$ 60.00 705m

Labour		
1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	
		\$ 800.00 600
2	To putty and spray Spray Paintings charges.	
		\$ 800.00 600
3	To check wirings and lightings.	
		\$ 40.00 200
4	To remove, refit & reset reverses sensors.	
		\$ 80.00 600
5	To remove, refit rear upholstery & attachments.	
		\$ 120.00 600
6	To remove, refit rear RH lower exhaust silencer.	
		\$ Bu 80.00 X
7	To supply and apply anti rust treatment	
		\$ 80.00 600
Total :		
		\$ 2,000.00

Total Parts and Labour : \$ 9,380.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: