

Vehicle Number : SMN4284T
Vehicle Model : SKODA SUPERB 1.8 TSI
Accident Date : 20.09.2024
Original Reg Date : 08.08.2019

Date : 27.09.2024
Chassis : TMBBL7NP9K7046550
TP Ins. LONPAC

Xiao Tony

ESTIMATE

1	1 pc	BOOTLID logo		165.90	✓
2	1 pc	BOOTLID SKODA emblem		145.60	✓
3	1 pc	BOOTLID SUPERB emblem		132.90	✓
4	1 pc	BOOTLID weatherstrip		318.60	✓
5	1 pc	SMART KEY ANTENNA		385.60	✓
6	1 pc	Rear bumper		2,965.76	✓
7	1 pc	Rear lower bumper		1,468.60	✓
8	1 pc	Rear bumper centre chrome strip		438.50	+
9	2 pc	Rear bumper lower cover	345.90	691.80	+
10	2 pc	Rear bumper reflectors	234.60	469.20	+
11	1 pc	Rear bumper reinforcement		1,017.60	✓
12	1 pc	Rear bumper centre retainer		356.90	✓
13	2 pc	Rear bumper retainers	198.60	397.20	+
14	4 pc	Rear bumper reverse sensor	385.60	1,542.40	+
15	4 pc	Rear bumper reverse sensor holders	48.60	194.40	+
16	1 pc	Rear bumper reverse sensor wirehardness		987.60	+
17	2 pc	Rear fender inner cowling	286.90	573.80	+
18	2 pc	Rear fender inner trims	685.30	1,370.60	+
19	2 pc	Tailamps	1,345.60	2,691.20	✓
20	2 pc	Tailamps inner sealer	40.00	80.00	+
21	2 pc	Tailamps brackets	205.80	411.60	+
22	1 pc	End panel		1,345.60	+
23	1 pc	End panel top garnish		286.90	+
24	1 pc	spare tyre floor panel		1,145.60	+
25	1 pc	spare tyre floor panel top board		698.70	+
26	1 pc	Rear silencer box		1,345.20	+
27	2 pc	Rear silencer box mounting	86.30	172.60	+
28	1 pc	Rear silencer box heat shield		398.20	+
				subtotal	22,198.56

6704.20
6033.78

Special Nett

1	1 pc	Rear number plate with casing		50.00	+
2	1 set	Rear bumper clips		30.00	✓
3	2 set	Rear fender inner cowling clips	30.00	60.00	+
4	2 set	Rear fender inner trim clips	30.00	60.00	+
5	2 set	Tailamps clips	30.00	60.00	+
6	1 set	end panel top garnish clips		30.00	+

7	1 set	floor panel insulator pads	$\left\{ \begin{array}{l} NP \\ \downarrow \\ ne \end{array} \right.$	100.00	+
8	1 set	end panel sealant		60.00	+

30

Labour charge

Panel Beating	1,400.00	400
Spray painting	1,400.00	600
Check Wiring on tailamp	120.00	30
Anti rust	100.00	+
Remove and install reverse sensor	120.00	50
Remove and install rear bootlid and mechanism	150.00	+
Remove and install rear silencer box	150.00	+
Remove and install interior upholstery	150.00	+

1080

total 26,238.56

Admin L
1/5 27/09/24
04 days

total: 5143.78
1/5: 5.7K

5.7K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: